

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-006692	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 10/05/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 21:20 Hrs.	Private Property: No	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: DEPUTY BRAD STEVENS	Acc Loc City:	Distance 2:
Badge #: 71-10	Acc Dir From City:	Direction 2:
Report Date: 10/05/2017	Closest City:	X-Coordinate: 00296203
Officer Notified: 21:26 Hrs.	Miles From City:	Y-Coordinate: 04778073
Officer Arrived: 21:36 Hrs.	Road, Street, HWay:	Location Literal: VAN BUREN AVE AND
Scene Investigated: Yes	Definable Location:	Description: B024/360TH ST
	Milepost Number:	

Unit 001

Driver Name - Last: MCDONALD	Bus Use:	Transported to: NONE
First: JAMES		
Middle: RONALD	Drvr Distractions: 02 - Not distracted	Transported by: N/A
City: OCHEYEDAN		
State: IA	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
Zip: 51354-0000		
Suffix:	Point of Init 03 - Middle Passenger Side	Emergency Status: 01 - Not applicable
Gender: Male	Impact:	
Age: 60	Most Damaged 03 - Middle Passenger Side	Cont. Circum., Drvr: 06 - Lost control
CDL: Yes	Area:	
License State: IA	Undrrid/Ovrid: 1 - None	
License Class: A	Rpr/Rplc Cost: \$37,812.00	Carrier Name: COOPERATIVE FARMERS ELE
License Endorsmnt: T - Dbl/Trpl Trlr	Ext of Damage: 4 - Disabling damage	Carrier Address: 1219 MAIN ST
License Restrictions: B	First Event: 01 - Ran off road, right	Carrier City: ROCK VALLEY
Speed Limit: 55		Carrier State: IA
Seating Position: 01 - 1st row: left side/motorcycle driver	Second Event: 20 - Overturn/rollover	Carrier Zip: 51247
Driver Condition: 01 - Apparently normal		Cargo Body Type: 03 - Dump (grain/gravel)
Alcohol Test Given: NO	Third Event:	
Drug Test Given: 1 - None		
Total Occupants: 1	Fourth Event:	Number of Axles: 5
Vehicle Year: 2006		HazMat Involvement: 02 - No
Vehicle Make: Peterbilt - PTRB	Most Harmful 20 - Overturn/rollover	HazMat Placard:
Vehicle Model: SEMI	Event:	Placard #:
Vehicle Style: SEMI	Abg Switch Stat:	HazMat Released?:
Vehicle Color: WHITE - WHI	Abg Deploy: 01 - Not applicable	Converter Dolly: 2
Vehicle Config: 08 - Single-unit truck (>=3 axles)		GVWR: 3 - 26,001 lbs or more
Vehicle Defect: 01 - None	Trapped: 1 - Not trapped/applicable	Cit Chrg Code 1:
Vehicle Action: 03 - Turning right	Ejection: 1 - Not applicable	Citation Charge 1:
Tow: 6 - Abandoned/left at scene	Ejection Path: 01 - Not ejected/not applicable	Cit Chrg Code 2:
Tow #:	Occpnt Protect: 03 - Shoulder and lap belt used	Citation Charge 2:
Initial Trvl Dir: 04 - West	Injury Status: 5 - Uninjured	Cit Chrg Code 3:
Vision Obscured: 01 - Not obscured		Citation Charge 3:
	Source of Trans: 01 - Not Transported	Cit Chrg Code 4:
	Died at Scene: 01 - Not applicable	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - On roadway	Roadway Characteristics
Manner of Crash/Collision: 01 - Non-collision (single vehicle)	Environment: 01 - None apparent
Light Conditions: 5 - Dark, roadway not lighted	Roadway: 01 - None apparent
Weather Conditions: 05 - Rain	
Surface Conditions: 02 - Wet	Type of Road Junc/Feat: 12 - Four-way intersection
Workzone Related: No	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: 20 - Overturn/rollover
Workers Present:	

Narrative

Unit 1 was westbound on 360th Street. Unit 1 attempted to turn north onto Van Buren Avenue and turned too sharply causing both tractor and trailer to turn onto it's side coming to rest in the east ditch.

Diagram

