

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>17-007998</b>	Report to All Drivers:	<b>Yes</b>	At Intersection with:	
Date of Acc:	<b>12/07/17</b>	Legal Intervention:	<b>No</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>05:01</b> Hrs.	Private Property:	<b>No</b>	Distance 1:	
Name of Agency:	<b>O'Brien County Sheriff's Off</b>	County:	<b>O'Brien - 71</b>	Direction 1:	
Officer:	<b>VANMEETEREN KEVEN</b>	Acc Loc City:		Distance 2:	
Badge #:	<b>71-7</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>12/07/2017</b>	Closest City:		X-Coordinate:	<b>00298062</b>
Officer Notified:	<b>05:01</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04757819</b>
Officer Arrived:	<b>05:15</b> Hrs.	Road, Street, HWay:		Location Literal:	<b>6658 HWY 10 BLVD</b>
Scene Investigated:	<b>Yes</b>	Definable Location:		Description:	
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>BROWN</b>	Bus Use:		Transported to:	<b>N/A</b>
First:	<b>MICHAEL</b>	Drvr Distractions:	<b>02 - Not distracted</b>	Transported by:	<b>N/A</b>
Middle:	<b>JAMES</b>	Traffic Controls:	<b>01 - No controls present</b>	Special Veh Func:	<b>01 - No special function</b>
City:	<b>SUTHERLAND</b>	Point of Init Impact:	<b>01 - Front Passenger Side Corner</b>	Emergency Status:	<b>01 - Not applicable</b>
State:	<b>IA</b>	Most Damaged Area:	<b>01 - Front Passenger Side Corner</b>	Cont. Circum., Drvr:	<b>88 - No improper action</b>
Zip:	<b>51058-0000</b>	Undrrid/Ovrid:	<b>1 - None</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$6,000.00</b>	Carrier Address:	
Gender:	<b>Male</b>	Ext of Damage:	<b>3 - Functional damage</b>	Carrier City:	
Age:	<b>66</b>	First Event:	<b>06 - Evasive action (swerve, panic braking, avoidance)</b>	Carrier State:	
CDL:	<b>No</b>	Second Event:	<b>31 - Animal</b>	Carrier Zip:	
License State:	<b>IA</b>	Third Event:		Cargo Body Type:	<b>01 - Not applicable</b>
License Class:	<b>D</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:	<b>3 - Pass Veh less than 16 Pass</b>	Most Harmful Event:	<b>31 - Animal</b>	HazMat Involvement:	
License Restrictions:	<b>B</b>	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>55</b>	Abg Deploy:	<b>03 - Not deployed</b>	Placard #:	
Seating Position:	<b>01 - 1st row: left side/motorcycle driver</b>	Trapped:	<b>1 - Not trapped/applicable</b>	HazMat Released?:	
Driver Condition:	<b>01 - Apparently normal</b>	Ejection:	<b>2 - Not ejected</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - Not ejected/not applicable</b>	GVWR:	
Drug Test Given:	<b>1 - None</b>	Occpnt Protect:	<b>03 - Shoulder and lap belt used</b>	Cit Chrg Code 1:	
Total Occupants:	<b>01</b>	Injury Status:	<b>4 - Possible (complaint of pain/injury)</b>	Citation Charge 1:	
Vehicle Year:	<b>2009</b>	Source of Trans:	<b>01 - Not Transported</b>	Citation Charge 2:	
Vehicle Make:	<b>Ford - FORD</b>	Died at Scene:	<b>01 - Not applicable</b>	Citation Charge 3:	
Vehicle Model:	<b>EDG</b>			Citation Charge 4:	
Vehicle Style:	<b>SW</b>				
Vehicle Color:	<b>SILVER - SIL</b>				
Vehicle Config:	<b>03 - Sport utility vehicle</b>				
Vehicle Defect:	<b>01 - None</b>				
Vehicle Action:	<b>01 - Movement essentially straight</b>				
Tow:	<b>1 - Driven away</b>				
Tow #:					
Initial Trvl Dir:	<b>02 - East</b>				
Vision Obscured:	<b>01 - Not obscured</b>				

**Property Damage 001**

Object Damaged:	<b>550 LB STEER</b>	Company Owner Name:	
Estimate of Damage:	<b>\$900.00</b>	City:	<b>SUTHERLAND</b>
Owner's Name - Last:	<b>DREFKE</b>	State:	<b>IA</b>
First:	<b>MARK</b>	Zip Code:	<b>51058</b>
Middle:			
Suffix:			

**Accident Environment**

First Harmful Event Loc:	<b>01 - On roadway</b>	<b>Roadway Characteristics</b>	
Manner of Crash/Collision:	<b>01 - Non-collision (single vehicle)</b>	Environment:	<b>06 - Animal in roadway</b>
Light Conditions:	<b>5 - Dark, roadway not lighted</b>	Roadway:	<b>01 - None apparent</b>
Weather Conditions:	<b>01 - Clear</b>	Type of Road Junc/Feat:	<b>01 - Non-junction/no special feature</b>
Surface Conditions:	<b>01 - Dry</b>	FRA No.:	
Workzone Related:	<b>No</b>	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	<b>31 - Animal</b>
Type:			
Workers Present:			

**Narrative**

Unit 1 was eastbound on Hwy 10 Blvd and struck a 550lb steer that was on the roadway.



Diagram

not to scale

