

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-002345	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 04/22/18	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 09:30 Hrs.	Private Property: No	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: VANDERVEEN STEVEN	Acc Loc City:	Distance 2:
Badge #: 71-9	Acc Dir From City:	Direction 2:
Report Date: 04/22/2018	Closest City:	X-Coordinate: 00297449
Officer Notified: 09:42 Hrs.	Miles From City:	Y-Coordinate: 04769546
Officer Arrived: 09:48 Hrs.	Road, Street, HWay:	Location Literal: M012/VINE AVE
Scene Investigated: Yes	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: HAGOS	Bus Use:	Transported to: PRIMGHAR HOSPITAL
First: MULUGETA	Drvr Distractions: 99 - Unknown	Transported by: SUTHERLAND AMBULANCE
Middle: TESFAHIWOT	Traffic Controls: 06 - No Passing Zone (marked)	Special Veh Func: 01 - No special function
City: SIOUX FALLS	Point of Init Impact: 12 - Front Middle	Emergency Status: 01 - Not applicable
State: SD	Most Damaged Area: 12 - Front Middle	Cont. Circum., Drvr: 06 - Lost control
Zip: 57103-2095	Undrrid/Ovrid: 1 - None	Carrier Name:
Suffix:	Rpr/Rplc Cost: \$9,000.00	Carrier Address:
Gender: Male	Ext of Damage: 5 - Severe, vehicle totaled	Carrier City:
Age: 31	First Event: 01 - Ran off road, right	Carrier State:
CDL: No	Second Event: 06 - Evasive action (swerve, panic braking, avoidance)	Carrier Zip:
License State: SD	Third Event: 03 - Ran off road, left	Cargo Body Type: 01 - Not applicable
License Class: 1	Fourth Event: 60 - Tree	Number of Axles:
License Endorsmnt:	Most Harmful Event: 60 - Tree	HazMat Involvement:
License Restrictions:	Abg Switch Stat:	HazMat Placard:
Speed Limit: 55	Abg Deploy: 04 - Deployed front of person	Placard #:
Seating Position: 01 - 1st row: left side/motorcycle driver	Trapped: 1 - Not trapped/applicable	HazMat Released?:
Driver Condition: 01 - Apparently normal	Ejection: 2 - Not ejected	Converter Dolly:
Alcohol Test Given: NO	Ejection Path: 01 - Not ejected/not applicable	GVWR:
Drug Test Given: 1 - None	Occpnt Protect: 03 - Shoulder and lap belt used	Cit Chrg Code 1: 321.288(1)
Total Occupants: 1	Injury Status: 3 - Suspected minor/non-incapacitating	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Vehicle Year: 2005	Source of Trans: 03 - EMS ground	Cit Chrg Code 2:
Vehicle Make: Hyundai - HYUN	Died at Scene: 01 - Not applicable	Cit Chrg Code 3:
Vehicle Model: TUCSON		Citation Charge 3:
Vehicle Style: SUV		Cit Chrg Code 4:
Vehicle Color: SILVER - SIL		Citation Charge 4:
Vehicle Config: 03 - Sport utility vehicle		
Vehicle Defect: 01 - None		
Vehicle Action: 01 - Movement essentially straight		
Tow: 3 - Disabled - officer arranged		
Tow #: 18-00028		
Initial Trvl Dir: 03 - South		
Vision Obscured: 01 - Not obscured		

Accident Environment

First Harmful Event Loc: 02 - Shoulder	Roadway Characteristics
Manner of Crash/Collision: 01 - Non-collision (single vehicle)	Environment: 01 - None apparent
Light Conditions: 1 - Daylight	Roadway: 01 - None apparent
Weather Conditions: 01 - Clear	Type of Road Junc/Feat: 01 - Non-junction/no special feature
Surface Conditions: 01 - Dry	FRA No.:
Workzone Related: No	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 60 - Tree
Type:	
Workers Present:	

Narrative

Vehicle #1 was southbound on Vine Avenue (M-12). It appears the driver dropped off the right shoulder of the road. The driver then over corrected the vehicle and went into the east ditch. Vehicle #1 then impacted a tree.

Diagram

