

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: S17-008415	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 12/29/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 10:38 Hrs.	Private Property: No	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: VANMEETEREN KEVEN	Acc Loc City:	Distance 2:
Badge #: 71-7	Acc Dir From City:	Direction 2:
Report Date: 12/29/2017	Closest City:	X-Coordinate: 00286747
Officer Notified: 10:40 Hrs.	Miles From City:	Y-Coordinate: 04784776
Officer Arrived: 10:51 Hrs.	Road, Street, HWay:	Location Literal: US 59/SILVER AVE
Scene Investigated: Yes	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: HANSEN	Bus Use:	Transported to: N/A
First: CHERYL	Drvr Distractions: 02 - Not distracted	Transported by: N/A
Middle: JEAN	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
City: PRIMGHAR	Point of Init Impact: 11 - Front Driver Side Corner	Emergency Status: 01 - Not applicable
State: IA	Most Damaged Area: 11 - Front Driver Side Corner	Cont. Circum., Drvr: 06 - Lost control
Zip: 51245-0000	Undrrid/Ovrid: 1 - None	Carrier Name:
Suffix:	Rpr/Rplc Cost: \$5,000.00	Carrier Address:
Gender: Female	Ext of Damage: 3 - Functional damage	Carrier City:
Age: 52	First Event: 06 - Evasive action (swerve, panic braking, avoidance)	Carrier State:
CDL: No	Second Event: 33 - Vehicle in traffic	Carrier Zip:
License State: IA	Third Event:	Cargo Body Type: 01 - Not applicable
License Class: C	Fourth Event:	Number of Axles:
License Endorsmnt: P - Pass	Most Harmful Event: 33 - Vehicle in traffic	HazMat Involvement:
License Restrictions: KLN	Abg Switch Stat:	HazMat Placard:
Speed Limit: 55	Abg Deploy: 03 - Not deployed	Placard #:
Seating Position: 01 - 1st row: left side/motorcycle driver	Trapped: 1 - Not trapped/applicable	HazMat Released?:
Driver Condition: 01 - Apparently normal	Ejection: 2 - Not ejected	Converter Dolly:
Alcohol Test Given: NO	Ejection Path: 01 - Not ejected/not applicable	GVWR:
Drug Test Given: 1 - None	Occpnt Protect: 03 - Shoulder and lap belt used	Cit Chrg Code 1: 321.288(1)
Total Occupants: 01	Injury Status: 5 - Uninjured	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Vehicle Year: 2011	Source of Trans: 01 - Not Transported	Cit Chrg Code 2:
Vehicle Make: Toyota - TOYT	Died at Scene: 01 - Not applicable	Citation Charge 2:
Vehicle Model: HGH		Cit Chrg Code 3:
Vehicle Style: SW		Citation Charge 3:
Vehicle Color: GRAY - GRY		Cit Chrg Code 4:
Vehicle Config: 03 - Sport utility vehicle		Citation Charge 4:
Vehicle Defect: 01 - None		
Vehicle Action: 03 - Turning right		
Tow: 1 - Driven away		
Tow #: 02 - East		
Initial Trvl Dir: 01 - Not obscured		
Vision Obscured: 01 - Not obscured		

Unit 002

Driver Name - Last: LEFRANCIS	Bus Use:	Transported to: N/A
First: LESLEE		
Middle: MAE	Drvr Distractions: 02 - Not distracted	Transported by: N/A
City: PRIMGHAR		
State: IA	Traffic Controls: 04 - Stop signs	Special Veh Func: 01 - No special function
Zip: 51245-0000		
Suffix:	Point of Init Impact: 07 - Rear Driver Side Corner	Emergency Status: 01 - Not applicable
Gender: Female	Most Damaged Area: 07 - Rear Driver Side Corner	Cont. Circum., Drvr: 88 - No improper action
Age: 43	Undrdr/Ovrid: 1 - None	
CDL: No	Rpr/Rplc Cost: \$500.00	
License State: IA	Ext of Damage: 3 - Functional damage	
License Class: C	First Event: 06 - Evasive action (swerve, panic braking, avoidance)	Carrier Name:
License Endorsmnt: B		Carrier Address:
License Restrictions: B	Second Event: 33 - Vehicle in traffic	Carrier City:
Speed Limit: 55		Carrier State:
Seating Position: 01 - 1st row: left side/motorcycle driver	Third Event:	Carrier Zip:
Driver Condition: 01 - Apparently normal	Fourth Event:	Cargo Body Type: 01 - Not applicable
Alcohol Test Given: NO		
Drug Test Given: 1 - None	Most Harmful Event: 33 - Vehicle in traffic	Number of Axles:
Total Occupants: 01		HazMat Involvement:
Vehicle Year: 1999	Abg Switch Stat:	HazMat Placard:
Vehicle Make: General Motors - GMC	Abg Deploy: 03 - Not deployed	Placard #:
Vehicle Model: JMY		HazMat Released?:
Vehicle Style: SW	Trapped: 1 - Not trapped/applicable	Converter Dolly:
Vehicle Color: BLACK - BLK	Ejection: 1 - Not applicable	GVWR:
Vehicle Config: 03 - Sport utility vehicle	Ejection Path: 01 - Not ejected/not applicable	Cit Chrg Code 1: 321.20B
Vehicle Defect: 01 - None	Occpnt Protect: 03 - Shoulder and lap belt used	Citation Charge 1: FAILURE TO PROVIDE PROOF OF FINANCIAL LIABILITY - ACC
Vehicle Action: 10 - Slowing/stopping (decelerating)	Injury Status: 5 - Uninjured	Cit Chrg Code 2:
Tow: 1 - Driven away	Source of Trans: 01 - Not Transported	Citation Charge 2:
Tow #:	Died at Scene: 01 - Not applicable	Cit Chrg Code 3:
Initial Trvl Dir: 01 - North		Citation Charge 3:
Vision Obscured: 01 - Not obscured		Cit Chrg Code 4:
		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - On roadway	Roadway Characteristics
Manner of Crash/Collision: 03 - Rear end (front to rear)	Environment: 02 - Weather condition
Light Conditions: 1 - Daylight	Roadway: 02 - Surface condition (e.g., wet, icy)
Weather Conditions: 07 - Snow	Type of Road Junc/Feat: 12 - Four-way intersection
Surface Conditions: 04 - Snow	FRA No.:
	Horizontal Alignment:
Workzone Related: No	Vertical Alignment:
Activity:	First Harmful Evt of Crash: 33 - Vehicle in traffic
Location:	
Type:	
Workers Present:	

Narrative

Unit 1 was slowing to make a right hand turn from Hwy 18 onto Hwy 59 to go south. Due to the snow covered/slippery road conditions driver of Unit 1 was unable to make the turn and slid into the intersection and struck Unit 2 that was stopping for the northbound stop sign at the Hwy 18/59 intersection.

