

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	18-007716	Report to All Drivers:		At Intersection with:	
Date of Acc:	11/29/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	09:28 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	BRACY DANIEL	Acc Loc City:		Distance 2:	
Badge #:	71-6	Acc Dir From City:		Direction 2:	
Report Date:	11/29/2018	Closest City:		X-Coordinate:	00297393
Officer Notified:	09:29 Hrs.	Miles From City:		Y-Coordinate:	04767745
Officer Arrived:	09:47 Hrs.	Road, Street, HWay:		Location Literal:	M012/VINE AVE
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	HUITRON	Bus Use:		Transported to:	
First:	ESBER	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:		Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	OMAHA	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	NE	Most Damaged Area:	07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr:	05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Zip:	68111-0000	Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$5,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	3 - FUNCTIONAL DAMAGE	Carrier City:	
Age:	43	First Event:	01 - RAN OFF ROAD, RIGHT	Carrier State:	
CDL:	NO	Second Event:	44 - DITCH	Carrier Zip:	
License State:	NE	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	ID	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	44 - DITCH	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	321.174(1)
Total Occupants:	2	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	NO VALID DRIVERS LICENSE
Vehicle Year:	2009	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	321.288(1)
Vehicle Make:	CHEVROLET - CHEV			Citation Charge 2:	FAILURE TO MAINTAIN CONTROL
Vehicle Model:	SILV			Citation Charge 3:	
Vehicle Style:	PICKUP			Citation Charge 4:	
Vehicle Color:	RED - RED				
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	02 - SHOULDER	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	02 - WEATHER CONDITION
Light Conditions:	1 - DAYLIGHT	Roadway:	06 - SLIPPERY, LOOSE, OR WORN SURFACE
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	03 - ICE/FROST	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

UNIT 001 WAS SOUTHBOUND IN THE 4200 MILE OF VINE AVE PULLING TRAILER WITH IA PLATE "GA8598"; UNIT 001 LOST CONTROL ON THE ICE AND ENTERED THE WEST DITCH FACING SOUTHBOUND; DRIVER OF UNIT 001 UNHOOKED THE TRAILER FROM THE UNIT 001 BEFORE I ARRIVED ON SCENE; DRIVER OF UNIT 001 ADMITTED TO NOT HAVING A VALID DRIVERS LICENSE; OWNER OF TRAILER INFORMED ME THAT THERE WERE APPROXIMATELY \$25,000 WORTH OF FLAT ROOFING ROBOTS INSIDE THE TRAILER THAT THEY WONT KNOW IF THEY ARE DAMAGED UNTIL THE GO TO USE THEM; THE CONTRACTORS NAME IS CHAD WUEBKER AND CONTACT # 712-331-4365

Diagram

