

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	17-006872	Report to All Drivers:	Yes	At Intersection with:	
Date of Acc:	10/13/17	Legal Intervention:	No	Div HWay Trvl Dir:	
Time of Acc:	16:30 Hrs.	Private Property:	No	Distance 1:	
Name of Agency:	O'Brien County Sheriff's Off	County:	O'Brien - 71	Direction 1:	
Officer:	DEPUTY BRAD STEVENS	Acc Loc City:		Distance 2:	
Badge #:	71-10	Acc Dir From City:		Direction 2:	
Report Date:	10/13/2017	Closest City:		X-Coordinate:	00283708
Officer Notified:	16:32 Hrs.	Miles From City:		Y-Coordinate:	04790600
Officer Arrived:	16:47 Hrs.	Road, Street, HWay:		Location Literal:	REDWOOD AVE
Scene Investigated:	Yes	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	HARPER	Bus Use:		Transported to:	
First:	JARREN	Drvr Distractions:	14 - Reaching for object(s)/fallen object(s)	Transported by:	
Middle:	DANIEL	Traffic Controls:	01 - No controls present	Special Veh Func:	01 - No special function
City:	PAULLINA	Point of Init Impact:	02 - Front Passenger Side	Emergency Status:	01 - Not applicable
State:	IA	Most Damaged Area:	03 - Middle Passenger Side	Cont. Circum., Drvr:	06 - Lost control
Zip:	51046-0000	Undrrid/Ovrid:	1 - None	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$11,928.00	Carrier Address:	
Gender:	Male	Ext of Damage:	5 - Severe, vehicle totaled	Carrier City:	
Age:	17	First Event:	06 - Evasive action (swerve, panic braking, avoidance)	Carrier State:	
CDL:	No	Second Event:	01 - Ran off road, right	Carrier Zip:	
License State:	IA	Third Event:	20 - Overturn/rollover	Cargo Body Type:	01 - Not applicable
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	20 - Overturn/rollover	HazMat Involvement:	
License Restrictions:	Y	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	03 - Not deployed	Placard #:	
Seating Position:	01 - 1st row: left side/motorcycle driver	Trapped:	1 - Not trapped/applicable	HazMat Released?:	
Driver Condition:	01 - Apparently normal	Ejection:	2 - Not ejected	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - Not ejected/not applicable	GVWR:	
Drug Test Given:	1 - None	Occpnt Protect:	03 - Shoulder and lap belt used	Cit Chrg Code 1:	
Total Occupants:	1	Injury Status:	4 - Possible (complaint of pain/injury)	Citation Charge 1:	
Vehicle Year:	2004	Source of Trans:	01 - Not Transported	Cit Chrg Code 2:	
Vehicle Make:	Chevrolet - CHEV	Died at Scene:	01 - Not applicable	Citation Charge 2:	
Vehicle Model:	SLV			Cit Chrg Code 3:	
Vehicle Style:	PK			Citation Charge 3:	
Vehicle Color:	BLACK - BLK			Cit Chrg Code 4:	
Vehicle Config:	02 - Four-tire truck (pick-up)			Citation Charge 4:	
Vehicle Defect:	01 - None				
Vehicle Action:	01 - Movement essentially straight				
Tow:	3 - Disabled - officer arranged				
Tow #:	17000099				
Initial Trvl Dir:	01 - North				
Vision Obscured:	01 - Not obscured				

Accident Environment

First Harmful Event Loc:	01 - On roadway	Roadway Characteristics	
Manner of Crash/Collision:	01 - Non-collision (single vehicle)	Environment:	01 - None apparent
Light Conditions:	1 - Daylight	Roadway:	01 - None apparent
Weather Conditions:	01 - Clear	Type of Road Junc/Feat:	01 - Non-junction/no special feature
Surface Conditions:	01 - Dry	FRA No.:	
Workzone Related:	No	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	20 - Overturn/rollover
Type:			
Workers Present:			

Narrative

Unit 1 was northbound in the 2800 mile of Redwood Avenue. Driver was distracted by an unknown object near the brake and gas pedals. Driver reached down to move the unknown object and Unit 1 began to fishtail. Driver was unable to regain control and entered the east ditch where Unit 1 rolled coming to rest on the driver's side.

