

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>17-007768</b>	Report to All Drivers: <b>Yes</b>	At Intersection with:
Date of Acc: <b>11/24/17</b>	Legal Intervention: <b>No</b>	Div HWay Trvl Dir:
Time of Acc: <b>19:19 Hrs.</b>	Private Property: <b>No</b>	Distance 1:
Name of Agency: <b>O'Brien County Sheriff's Off</b>	County: <b>O'Brien - 71</b>	Direction 1:
Officer: <b>DEPUTY LEE REUVERS</b>	Acc Loc City:	Distance 2:
Badge #: <b>71-4</b>	Acc Dir From City:	Direction 2:
Report Date: <b>11/24/2017</b>	Closest City:	X-Coordinate: <b>00273982</b>
Officer Notified: <b>19:19 Hrs.</b>	Miles From City:	Y-Coordinate: <b>04783620</b>
Officer Arrived: <b>19:25 Hrs.</b>	Road, Street, HWay:	Location Literal: <b>330TH ST</b>
Scene Investigated: <b>Yes</b>	Definable Location:	Description:
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>STERLER</b>	Bus Use:	Transported to: <b>SHELDON HOSPITAL</b>
First: <b>TRAVIS</b>	Drvr Distractions: <b>11 - Unrestrained animal</b>	Transported by: <b>SHELDON AMBULANCE</b>
Middle: <b>JOHN</b>	Traffic Controls: <b>01 - No controls present</b>	Special Veh Func: <b>01 - No special function</b>
City: <b>SANBORN</b>	Point of Init Impact: <b>03 - Middle Passenger Side</b>	Emergency Status: <b>01 - Not applicable</b>
State: <b>IA</b>	Most Damaged Area: <b>03 - Middle Passenger Side</b>	Cont. Circum., Drvr: <b>06 - Lost control</b>
Zip: <b>51248-0000</b>	Undrrid/Ovrid: <b>1 - None</b>	Carrier Name:
Suffix:	Rpr/Rplc Cost: <b>\$4,000.00</b>	Carrier Address:
Gender: <b>Male</b>	Ext of Damage: <b>5 - Severe, vehicle totaled</b>	Carrier City:
Age: <b>20</b>	First Event: <b>13 - Animal (avoided hitting)</b>	Carrier State:
CDL: <b>No</b>	Second Event: <b>06 - Evasive action (swerve, panic braking, avoidance)</b>	Carrier Zip:
License State: <b>IA</b>	Third Event: <b>01 - Ran off road, right</b>	Cargo Body Type: <b>01 - Not applicable</b>
License Class: <b>C</b>	Fourth Event: <b>20 - Overturn/rollover</b>	Number of Axles:
License Endorsmnt:	Most Harmful Event: <b>20 - Overturn/rollover</b>	HazMat Involvement:
License Restrictions:	Abg Switch Stat:	HazMat Placard:
Speed Limit: <b>50</b>	Abg Deploy: <b>03 - Not deployed</b>	Placard #:
Seating Position: <b>01 - 1st row: left side/motorcycle driver</b>	Trapped: <b>1 - Not trapped/applicable</b>	HazMat Released?:
Driver Condition: <b>01 - Apparently normal</b>	Ejection: <b>2 - Not ejected</b>	Converter Dolly:
Alcohol Test Given: <b>NO</b>	Ejection Path: <b>01 - Not ejected/not applicable</b>	GVWR:
Drug Test Given: <b>1 - None</b>	Occpnt Protect: <b>99 - Unknown</b>	Cit Chrg Code 1:
Total Occupants: <b>1</b>	Injury Status: <b>3 - Suspected minor/non-incapacitating</b>	Citation Charge 1:
Vehicle Year: <b>2006</b>	Source of Trans: <b>03 - EMS ground</b>	Cit Chrg Code 2:
Vehicle Make: <b>Pontiac - PONT</b>	Died at Scene: <b>01 - Not applicable</b>	Citation Charge 2:
Vehicle Model: <b>G6</b>		Cit Chrg Code 3:
Vehicle Style: <b>4D</b>		Citation Charge 3:
Vehicle Color: <b>BLACK - BLK</b>		Cit Chrg Code 4:
Vehicle Config: <b>01 - Passenger car</b>		Citation Charge 4:
Vehicle Defect: <b>01 - None</b>		
Vehicle Action: <b>01 - Movement essentially straight</b>		
Tow: <b>3 - Disabled - officer arranged</b>		
Tow #: <b>17-00110</b>		
Initial Trvl Dir: <b>02 - East</b>		
Vision Obscured: <b>01 - Not obscured</b>		

**Accident Environment**

First Harmful Event Loc: <b>01 - On roadway</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>01 - Non-collision (single vehicle)</b>	Environment: <b>01 - None apparent</b>
Light Conditions: <b>5 - Dark, roadway not lighted</b>	Roadway: <b>01 - None apparent</b>
Weather Conditions: <b>01 - Clear</b>	Type of Road Junc/Feat: <b>01 - Non-junction/no special feature</b>
Surface Conditions: <b>01 - Dry</b>	FRA No.:
Workzone Related: <b>No</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>20 - Overturn/rollover</b>
Type:	
Workers Present:	

**Narrative**

VEHICLE WAS HEADING EAST ON 330TH WHEN A DEER RAN ACROSS THE ROAD JUST PRIOR TO OAK HILL AVE INTERSECTION. DRIVER SWERVED TO MISS DEER AND LOST CONTROL OF VEHICLE. VEHICLE ENTERED THE SOUTH DITCH AND ROLLED COMING TO REST ON ITS TIRES. EVERY SIDE OF THE VEHICLE WAS DAMAGED



Diagram

