

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	S20-007446	Report to All Drivers:		At Intersection with:	
Date of Acc:	10/31/20	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	22:15 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY KEVEN VANMEETEREN	Acc Loc City:		Distance 2:	
Badge #:	71-7	Acc Dir From City:		Direction 2:	
Report Date:	10/31/2020	Closest City:		X-Coordinate:	00298633
Officer Notified:	22:55 Hrs.	Miles From City:		Y-Coordinate:	04781287
Officer Arrived:	22:58 Hrs.	Road, Street, HWay:		Location Literal Description:	3395 WALNUT AVE
Scene Investigated:		Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	GELLERMAN	Bus Use:		Transported to:	N/A
First:	JAMES	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	N/A
Middle:	SAMUEL	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	HARTLEY	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	13 - TOP OF VEHICLE	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51346-0000	Undrriid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$4,500.00		
Gender:	Male	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier Name:	
Age:	14	First Event:	11 - LOSS OF TRACTION	Carrier Address:	
CDL:	NO	Second Event:	06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier City:	
License State:	IA	Third Event:	44 - DITCH	Carrier State:	
License Class:	C	Fourth Event:	20 - OVERTURN/ROLLOVER	Carrier Zip:	
License Endorsmnt:		Most Harmful Event:	20 - OVERTURN/ROLLOVER	Cargo Body Type:	01 - NOT APPLICABLE
License Restrictions:	2	Abg Switch Stat:		Number of Axles:	
Speed Limit:	50	Abg Deploy:	03 - NOT DEPLOYED	HazMat Involvement:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Placard:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Placard #:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Converter Dolly:	
Total Occupants:	02	Source of Trans:	01 - NOT TRANSPORTED	GVWR:	
Vehicle Year:	2005	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 1:	321.288(1)
Vehicle Make:	CHEVROLET - CHEV			Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Model:	EQUINOX			Cit Chrg Code 2:	321.180
Vehicle Style:	4DR WAGON			Citation Charge 2:	VIOLATION OF INSTRUCTION PERMIT LIMITATION
Vehicle Color:	TAN - TAN			Citation Charge 3:	
Vehicle Config:	03 - SPORT UTILITY VEHICLE			Citation Charge 4:	
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	20-00099				
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Property Damage 001

Object Damaged:	FENCE POST	Company Owner Name:	
Estimate of Damage:	\$250.00	City:	HARTLEY
Owner's Name - Last:	BACK	State:	IA
First:	LARRY	Zip Code:	51346
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	10 - GRAVEL	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	20 - OVERTURN/ROLLOVER
Type:			
Workers Present:			

Narrative

DRIVER OF UNIT 1 WAS SOUTHBOUND ON WALNUT AVE AND LOST CONTROL DUE TO SPEED AND INEXPERIENCE. DRIVER LOST CONTROL AND ENTERED

THE WEST DITCH, IMPACTING THE SIDE OF THE DITCH, THEN FLIPPING THE VEHICLE ONTO IT'S ROOF AND STRIKING A FENCE/FENCE POST AND COMING TO REST ON IT'S DRIVER'S SIDE.

Diagram

