

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	20-008701	Report to All Drivers:		At Intersection with:	
Date of Acc:	12/27/20	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	09:50 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY TIMOTHY ROHRBAUGH	Acc Loc City:		Distance 2:	
Badge #:	71-5	Acc Dir From City:		Direction 2:	
Report Date:	12/27/2020	Closest City:		X-Coordinate:	00271419
Officer Notified:	09:56 Hrs.	Miles From City:		Y-Coordinate:	04785849
Officer Arrived:	10:12 Hrs.	Road,Street,HWay:		Location Literal Description:	STATE 60/IOWA 60
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	MORALES BUCHAN SEBASTIAN	Bus Use:		Transported to:	
First:	SEBASTIAN	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:		Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SIBLEY	Point of Init Impact:	10 - FRONT DRIVER SIDE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	10 - FRONT DRIVER SIDE	Cont. Circum., Drvr:	05 - DRIVING TOO FAST FOR CONDITIONS
Zip:	51249	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$1,500.00	Carrier Name:	
Gender:	Male	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Address:	
Age:	29	First Event:	11 - LOSS OF TRACTION	Carrier City:	
CDL:	NO	Second Event:	01 - RAN OFF ROAD, RIGHT	Carrier State:	
License State:	NO	Third Event:	20 - OVERTURN/ROLLOVER	Carrier Zip:	
License Class:		Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:		Most Harmful Event:	11 - LOSS OF TRACTION	Number of Axles:	
License Restrictions:		Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	65	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	1 - NOT APPLICABLE	HazMat Released?:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	GVWR:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	321.288(1)
Vehicle Year:	2002	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Make:	FORD - FORD			Cit Chrg Code 2:	321.174(1)
Vehicle Model:	S10			Citation Charge 2:	NO VALID DRIVERS LICENSE
Vehicle Style:	PU			Citation Charge 3:	
Vehicle Color:	BLACK - BLK			Citation Charge 4:	
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	20-00128				
Initial Trvl Dir:	01 - NORTH				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	1 - DAYLIGHT	Roadway:	01 - NONE APPARENT
Weather Conditions:	07 - SNOW	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	04 - SNOW	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	20 - OVERTURN/ROLLOVER
Type:			
Workers Present:			

Narrative

THE VEHICLE WAS TRAVELING NORTH ENTERING HIGHWAY 60. LOST CONTROL ON THE SNOW AND ENTERED THE DITCH ROLLING THE VEHICLE ON ITS SIDE

Diagram

