

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Law Enforcement
 Case Number: **23-003607**
 Date of Acc: **06/04/23**
 Time of Acc: **08:55** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY LEE REUVERS**
 Badge #: **71-4**
 Report Date: **06/04/2023**
 Officer Notified: **08:55** Hrs.
 Officer Arrived: **09:08** Hrs.

Scene Investigated: **YES**
 Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00297518**
 Y-Coordinate: **04771954**
 Location Literal: **VINE AVE**
 Description:

Unit 001

Driver Name - Last: **EDWARDSON**
 First: **JOSHUA**
 Middle: **JEFFREY**
 City: **SPENCER**
 State: **IA**
 Zip: **51301**
 Suffix:
 Gender: **Male**
 Age: **21**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **03 - ASLEEP/FATIGUED**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2002**
 Vehicle Make: **CHEVROLET - CHEV**
 Vehicle Model: **MONTE CARLO SS**
 Vehicle Style: **2D**
 Vehicle Color: **BLACK - BLK**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **2 - DISABLED - PRIVATELY ARRANGED**
 Tow #:
 Initial Trvl Dir: **03 - SOUTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Drvr Distractions: **97 - OTHER DISTRACTION INSIDE VEHICLE (EXPLAIN IN NARRATIVE)**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **06 - REAR MIDDLE**
 Most Damaged Area: **06 - REAR MIDDLE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,500.00**
 Ext of Damage: **9 - UNKNOWN**
 First Event: **01 - RAN OFF ROAD, RIGHT**
 Second Event: **04 - CROSSED CENTERLINE (UNDIVIDED)**
 Third Event: **01 - RAN OFF ROAD, RIGHT**
 Fourth Event: **44 - DITCH**
 Most Harmful Event: **44 - DITCH**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **99 - UNKNOWN**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Drvr: **06 - LOST CONTROL, 09 - IMPROPER OR ERRATIC LANE CHANGING**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1: **321.288(1)**
 Citation Charge 1: **FAILURE TO MAINTAIN CONTROL**
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Accident Environment

First Harmful Event Loc: **02 - SHOULDER**
 Manner of Crash/Collision: **01 - NON-COLLISION (SINGLE VEHICLE)**
 Light Conditions: **1 - DAYLIGHT**
 Weather Conditions: **01 - CLEAR**
 Surface Conditions: **01 - DRY**
 Workzone Related: **NO**
 Activity:
 Location:
 Type:
 Workers Present:

Roadway Characteristics
 Environment: **01 - NONE APPARENT**
 Roadway: **01 - NONE APPARENT**
 Type of Road Junc/Feat: **01 - NON-JUNCTION/NO SPECIAL FEATURE**
 FRA No.:
 Horizontal Alignment:
 Vertical Alignment:
 First Harmful Evt of Crash: **44 - DITCH**

Narrative

Vehicle was heading northbound and turned around on a field driveway on Vine Ave and started to head southbound when driver, Joshua, lost control and entered the west ditch. Driver attempted to get out and become stuck. Driver left the scene and vehicle was located by a nearby resident at 8:55am. Alcohol believed to be a factor for accident, but due to evidence chain of custody issues, not charged.

Diagram

