

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-005418	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	09/19/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	06:44 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	DEPUTY KEVEN VANMEETEREN	Acc Loc City:		Distance 2:	"N/A"
Badge #:	71-7	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	09/19/2016	Closest City:	"N/A"	X-Coordinate:	00303925
Officer Notified:	06:44 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04754811
Officer Arrived:	07:06 Hrs.	Road,Street,HWay:	"N/A"	Location Literal	7000-BLK HWY 10 BLVD
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	WITTKOP	Bus Use:		Transported to:	
First:	ASHLEY	Drvtr Distractions:	01 - NOT APPLICABLE/NO DRIVER	Transported by:	
Middle:	ANN	Traffic Controls:		Special Veh Func:	
City:	SHELDON	Point of Init Impact:		Emergency Status:	
State:	IA	Most Damaged Area:		Cont. Circum., Drvr:	
Zip:	51201-0000	Undridd/Ovrid:			
Suffix:		Rpr/Rplc Cost:	\$5,500.00		
Gender:	Female	Ext of Damage:		Carrier Name:	
Age:	22	First Event:		Carrier Address:	
CDL:	NO	Second Event:		Carrier City:	
License State:	IA	Third Event:		Carrier State:	
License Class:	D	Fourth Event:		Carrier Zip:	
License Endorsmnt:	3 - PASS VEH LESS THAN 16	Most Harmful Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Restrictions:	PASS DESIGN NONE	Abg Switch Stat:		Number of Axles:	
Speed Limit:		Abg Deploy:		HazMat Involvement:	
Seating Position:		Trapped:		HazMat Placard:	
Driver Condition:		Ejection:		Placard #:	
Alcohol Test Given:	NO	Ejection Path:		HazMat Released?:	
Drug Test Given:	1 - NONE	Occpnt Protect:		Converter Dolly:	
Total Occupants:	01	Injury Status:		GVWR:	
Vehicle Year:	2015	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	
Vehicle Make:	CHEVROLET - CHEV	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	
Vehicle Model:	S1L			Cit Chrg Code 2:	
Vehicle Style:				Citation Charge 2:	
Vehicle Color:	WHITE - WHI			Cit Chrg Code 3:	
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 3:	
Vehicle Defect:				Cit Chrg Code 4:	
Vehicle Action:				Citation Charge 4:	
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	16-5418				
Initial Trvl Dir:					
Vision Obscured:					

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash:
Type:	31 - ANIMAL
Workers Present:	

Narrative

UNIT 1 EASTBOUND ON HWY 10 BLVD AND STRUCK A DEER THAT CAME OUT OF THE SOUTH DITCH.

