

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **16-005488**
 Date of Acc: **09/22/16**
 Time of Acc: **08:45** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY ZACHARY LARSEN**
 Badge #: **71-3**
 Report Date: **09/22/2016**
 Officer Notified: **08:56** Hrs.
 Officer Arrived: **09:13** Hrs.
 Scene Investigated: **YES**

Report to All Drivers: **YES**
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City: **"N/A"**
 Closest City: **"N/A"**
 Miles From City: **"N/A"**
 Road,Street,HWay: **"N/A"**
 Definable Location: **"N/A"**
 Milepost Number: **"N/A"**

At Intersection with: **"N/A"**
 Div HWay Trvl Dir: **"N/A"**
 Distance 1: **"N/A"**
 Direction 1: **"N/A"**
 Distance 2: **"N/A"**
 Direction 2: **"N/A"**
 X-Coordinate: **00275060**
 Y-Coordinate: **04769306**
 Location Literal: **OLIVE AVE**
 Description:

Unit 001

Driver Name - Last: **DYKSTRA**
 First: **PERRY**
 Middle: **ALLEN**
 City: **LE MARS**
 State: **IA**
 Zip: **51031-0000**
 Suffix:
 Gender: **Male**
 Age: **69**
 CDL: **YES**
 License State: **IA**
 License Class: **A**
 License Endorsmnt: **LPX**
 License Restrictions: **BMJ**
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **01**
 Vehicle Year: **2004**
 Vehicle Make: **INTERNATIONAL - INTL**
 Vehicle Model:
 Vehicle Style: **PK**
 Vehicle Color: **WHITE - WHI**
 Vehicle Config: **07 - SINGLE-UNIT TRUCK (2-AXLE, 6-TIRE)**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **11 - STOPPED IN TRAFFIC**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **03 - SOUTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **02 - FRONT PASSENGER SIDE**
 Most Damaged Area: **14 - UNDERCARRIAGE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **01 - NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **1 - NOT APPLICABLE**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Injury Status: **5 - UNINJURED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **04 - CARGO TANK**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Cit Chrg Code 3:
 Citation Charge 3:
 Cit Chrg Code 4:
 Citation Charge 4:

Unit 002

Driver Name - Last: VANDERHEIDEN	Bus Use:	Transported to:
First: PAUL		
Middle: ERNEST	Drvr Distractions: 16 - LOOKED BUT DID NOT SEE	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51046-0000		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 98 - OTHER (EXPLAIN IN NARRATIVE)	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
Age: 56	Undrrid/Ovrid: 1 - NONE	
CDL:	Rpr/Rplc Cost: \$0.00	
License State: IA	Ext of Damage: 1 - NONE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name:
License Endorsmnt: N - TANK		Carrier Address:
License Restrictions: B		Carrier City:
Speed Limit: 55		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Zip:
		Cargo Body Type: 01 - NOT APPLICABLE
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE	Fourth Event:	HazMat Involvement:
Total Occupants: 01		HazMat Placard:
Vehicle Year: 2005	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Make: CATERPILLAR - CAT		HazMat Released?:
Vehicle Model: 140M	Abg Switch Stat:	Converter Dolly:
Vehicle Style: GRADER	Abg Deploy: 01 - NOT APPLICABLE	GVWR:
Vehicle Color: YELLOW - YEL		Cit Chrg Code 1:
Vehicle Config: 35 - MAINTENANCE/CONSTRUCTIO	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection: 1 - NOT APPLICABLE	
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Occpnt Protect: 01 - NOT APPLICABLE	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
	Injury Status: 5 - UNINJURED	Cit Chrg Code 3:
Tow #:		Citation Charge 3:
Initial Trvl Dir: 01 - NORTH	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 4:
Vision Obscured: 01 - NOT OBSCURED	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 07 - SIDESWIPE, OPPOSITE DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

VEHICLE #1 WAS TRAVELING SOUTH WHEN IT WAS MEETING VEHICLE #2, WHICH WAS ON IT'S SIDE OF THE ROAD HEADING NORTH. VEHICLE #1 WENT ONTO THE OPPOSITE SIDE OF THE ROADWAY AND STOPPED TO LET THE ROAD GRADER GO BY. THE DRIVER OF VEHICLE #2 DIDN'T SEE VEHICLE #1 AND SIDE SWIPED VEHICLE IT.

