

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-005822	Report to All Drivers:	NO	At Intersection with:	"N/A"
Date of Acc:	10/07/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	14:28 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	ROHRBAUGH TIMOTHY	Acc Loc City:	SHELDON - 6950	Distance 2:	"N/A"
Badge #:	71-5	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	10/07/2016	Closest City:	"N/A"	X-Coordinate:	00269066
Officer Notified:	14:28 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04785409
Officer Arrived:	14:39 Hrs.	Road,Street,HWay:	"N/A"	Location Literal	PARK ST & WASHINGTON AVE
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	COOMBS	Bus Use:		Transported to:	SANFORD SHELDON
First:	TANNER	Drvr Distractions:	99 - UNKNOWN	Transported by:	SAAM
Middle:	OREN	Traffic Controls:	02 - TRAFFIC SIGNALS	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	HOSPERS	Point of Init	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Impact:		Cont. Circum., Drvr:	99 - UNKNOWN
Zip:	51238-0000	Most Damaged Area:	12 - FRONT MIDDLE		
Suffix:		Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Gender:	Male	Rpr/Rplc Cost:	\$6,000.00	Carrier Address:	
Age:	19	Ext of Damage:	4 - DISABLING DAMAGE	Carrier City:	
CDL:	NO	First Event:	33 - VEHICLE IN TRAFFIC	Carrier State:	
License State:	IA	Second Event:	06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Zip:	
License Class:	C	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	NONE	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
Speed Limit:	35	Abg Switch Stat:		HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy:	01 - NOT APPLICABLE	Placard #:	
Driver Condition:	01 - APPARENTLY NORMAL	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Alcohol Test Given:	NO	Ejection:	1 - NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Total Occupants:	1	Occpnt Protect:	01 - NOT APPLICABLE	Cit Chrg Code 1:	321.174(1)
Vehicle Year:	2006	Injury Status:	3 - SUSPECTED MINOR/NON- INCAPACITATING	Citation Charge 1:	NO VALID D/L
Vehicle Make:	HARLEY DAVIDSON - HD	Source of Trans:	03 - EMS GROUND	Cit Chrg Code 2:	321.288(1)
Vehicle Model:	FLN	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	FAILURE TO MAINTAIN CONTROL
Vehicle Style:	MC			Cit Chrg Code 3:	
Vehicle Color:	BLACK - BLK			Citation Charge 3:	
Vehicle Config:	17 - MOTORCYCLE			Cit Chrg Code 4:	
Vehicle Defect:	01 - NONE			Citation Charge 4:	
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: DOMINQUEZ	Bus Use:	Transported to:
First: LUIS		
Middle: MIGUEL	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: HAWARDEN		
State: IA	Traffic Controls: 02 - TRAFFIC SIGNALS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51023		
Suffix:	Point of Init 06 - REAR MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Impact:	
Age: 19	Most Damaged 06 - REAR MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL: NO	Area:	
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$500.00	
License Endorsmnt: NONE	Ext of Damage: 2 - MINOR DAMAGE	
License Restrictions: NONE	First Event: 33 - VEHICLE IN TRAFFIC	
Speed Limit: 35		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Address:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier City:
Alcohol Test Given: NO	Third Event:	Carrier State:
Drug Test Given: 1 - NONE		Carrier Zip:
Total Occupants: 1	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Vehicle Year: 2010		Number of Axles:
Vehicle Make: DODGE - DODG	Most Harmful 33 - VEHICLE IN TRAFFIC	HazMat Involvement:
Vehicle Model: AVENGER SXT	Event:	HazMat Placard:
Vehicle Style: 4D		Placard #:
Vehicle Color: SILVER - SIL	Abg Switch Stat:	HazMat Released?:
Vehicle Config: 01 - PASSENGER CAR	Abg Deploy: 03 - NOT DEPLOYED	Converter Dolly:
Vehicle Defect: 01 - NONE		GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1:
Tow: 1 - DRIVEN AWAY	Ejection: 2 - NOT EJECTED	Citation Charge 1:
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow #:	Occpnt Protect: 99 - UNKNOWN	Citation Charge 2:
Initial Trvl Dir: 04 - WEST	Injury Status: 5 - UNINJURED	Cit Chrg Code 3:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 4:
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Vehicle #1 was traveling west in traffic. Vehicle #2 also traveling west, stopped at the traffic light and vehicle #1 ran into the back of him.

