

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-005948	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	10/15/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	14:17 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	DEPUTY ZACHARY LARSEN	Acc Loc City:		Distance 2:	"N/A"
Badge #:	71-3	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	10/15/2016	Closest City:	"N/A"	X-Coordinate:	00283590
Officer Notified:	14:17 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04786535
Officer Arrived:	14:34 Hrs.	Road,Street,HWay:	"N/A"	Location Literal	310TH ST AND REDWOOD AVE
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	HOOGERS	Bus Use:		Transported to:	
First:	ARNOLD	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	DARREL	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SHELDON	Point of Init	10 - FRONT DRIVER SIDE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Impact:		Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	51201-0000	Most Damaged Area:	99 - UNKNOWN		
Suffix:		Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Gender:	Male	Rpr/Rplc Cost:	\$4,500.00	Carrier Address:	
Age:	70	Ext of Damage:	2 - MINOR DAMAGE	Carrier City:	
CDL:	YES	First Event:	33 - VEHICLE IN TRAFFIC	Carrier State:	
License State:	IA	Second Event:		Carrier Zip:	
License Class:	A	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	NONE	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
Speed Limit:	55	Abg Switch Stat:		HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Driver Condition:	01 - APPARENTLY NORMAL	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Alcohol Test Given:	NO	Ejection:	1 - NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Total Occupants:	01	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Vehicle Year:	2016	Injury Status:	5 - UNINJURED	Citation Charge 1:	
Vehicle Make:	FORD - FORD	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 2:	
Vehicle Model:	F15	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Style:	PK			Cit Chrg Code 3:	
Vehicle Color:	RED - RED			Citation Charge 3:	
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)			Cit Chrg Code 4:	
Vehicle Defect:	01 - NONE			Citation Charge 4:	
Vehicle Action:	02 - TURNING LEFT				
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:	01 - NORTH				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: DAMMAN	Bus Use:	Transported to:
First: DAVID		
Middle: JOHN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SANBORN		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51248-0000		
Suffix:	Point of Init Impact: 03 - MIDDLE PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 03 - MIDDLE PASSENGER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 51	Undrrid/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rplc Cost: \$3,500.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 03 - RAN OFF ROAD, LEFT	
License Endorsmnt: NONE		Carrier Name:
License Restrictions: BK		Carrier Address:
Speed Limit: 55		Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier State:
		Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Fourth Event:	
Drug Test Given: 1 - NONE		Number of Axles:
Total Occupants: 01		HazMat Involvement:
Vehicle Year: 1999		HazMat Placard:
Vehicle Make: FORD - FORD	Most Harmful Event: 03 - RAN OFF ROAD, LEFT	Placard #:
Vehicle Model: RNG		HazMat Released?:
Vehicle Style: PK	Abg Switch Stat:	Converter Dolly:
Vehicle Color: BLACK - BLK	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Cit Chrg Code 1:
Vehicle Defect: 01 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
	Ejection: 1 - NOT APPLICABLE	
Vehicle Action: 05 - OVERTAKING/PASSING	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Tow: 1 - DRIVEN AWAY	Injury Status: 5 - UNINJURED	Cit Chrg Code 3:
		Citation Charge 3:
Tow #:	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 4:
Initial Trvl Dir: 01 - NORTH	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 10 - GRAVEL	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

VEHICLE #1 WAS STOPPED ON THE SIDE OF THE ROAD AND THE DRIVER WAS ON HIS CELL PHONE. THE DRIVER OF VEHICLE #2 WAS GOING AROUND THE STOPPED VEHICLE, WHEN THE DRIVER OF VEHICLE #1 PUT TRUCK IN GEAR AND TURNED LEFT. BOTH VEHICLE'S COLLIDED. VEHICLE #2 WENT INTO THE DITCH BUT DROVE OUT.

