

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-006142	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	10/26/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	06:10 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	VANDERVEEN STEVEN	Acc Loc City:		Distance 2:	"N/A"
Badge #:	71-9	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	10/26/2016	Closest City:	"N/A"	X-Coordinate:	00282026
Officer Notified:	06:23 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04773683
Officer Arrived:	06:39 Hrs.	Road,Street,HWay:	"N/A"	Location Literal:	B040/390TH ST
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	RUBIO-TOPETE	Bus Use:		Transported to:	PRIMGHAR HOSPITAL
First:	RICARDO	Drvr Distractions:	99 - UNKNOWN	Transported by:	PRIMGHAR AMBULANCE
Middle:		Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SHELDON	Point of Init Impact:	01 - FRONT PASSENGER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51201-0000	Undridd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$4,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	4 - DISABLING DAMAGE	Carrier City:	
Age:	39	First Event:	03 - RAN OFF ROAD, LEFT	Carrier State:	
CDL:	NO	Second Event:	44 - DITCH	Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:	NONE	Most Harmful Event:	44 - DITCH	HazMat Involvement:	
License Restrictions:	NONE	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	06 - DEPLOYED BOTH FRONT/SIDE	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	99 - UNKNOWN	Cit Chrg Code 1:	321.288(1)
Total Occupants:	1	Injury Status:	2 - SUSPECTED SERIOUS/INCAPACITATING	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Year:	2007	Source of Trans:	03 - EMS GROUND	Cit Chrg Code 2:	
Vehicle Make:	HONDA - HOND	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 3:	
Vehicle Model:	RGL			Cit Chrg Code 4:	
Vehicle Style:	PK			Citation Charge 4:	
Vehicle Color:	SILVER - SIL				
Vehicle Config:	03 - SPORT UTILITY VEHICLE				
Vehicle Defect:	99 - UNKNOWN				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	04 - ROADSIDE	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	02 - WET	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

Vehicle #1 was eastbound on 390th Street east of Redwing Ave. The driver drifted off the roadway to the left and entered the north ditch. Vehicle #1 impacted a private driveway which caused the airbags to deploy. The vehicle came to rest in a harvested field on the north side of the road.

