

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **16-006695**
 Date of Acc: **11/18/16**
 Time of Acc: **10:30** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **ROHRBAUGH TIMOTHY**
 Badge #: **71-5**
 Report Date: **11/18/2016**
 Officer Notified: **10:32** Hrs.
 Officer Arrived: **10:37** Hrs.
 Scene Investigated: **YES**

Report to All Drivers: **YES**
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City: **"N/A"**
 Closest City: **"N/A"**
 Miles From City: **"N/A"**
 Road, Street, HWay: **"N/A"**
 Definable Location: **"N/A"**
 Milepost Number: **"N/A"**

At Intersection with: **"N/A"**
 Div HWay Trvl Dir: **"N/A"**
 Distance 1: **"N/A"**
 Direction 1: **"N/A"**
 Distance 2: **"N/A"**
 Direction 2: **"N/A"**
 X-Coordinate: **00286229**
 Y-Coordinate: **04767950**
 Location Literal Description: **US 59/SILVER AVE**

Unit 001

Driver Name - Last: ALDEN	Bus Use:	Transported to:
First: JOHN		
Middle: ALFRED	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: BELLE PLAINE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 52208		
Suffix:	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 06 - LOST CONTROL
Age: 54	Undrrid/Ovrid: 1 - NONE	
CDL:	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 4 - DISABLING DAMAGE	
License Class: A	First Event: 33 - VEHICLE IN TRAFFIC	Carrier Name: SEWARD TRUCKING LLC
License Endorsmnt: N - TANK		Carrier Address: 29754 300THST
License Restrictions: B	Second Event: 11 - LOSS OF TRACTION	Carrier City: NEW PROVIDENCE
Speed Limit: 55	Third Event: 21 - JACKKNIFE	Carrier State: IA
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip: 50206
Driver Condition: 01 - APPARENTLY NORMAL	Most Harmful Event: 11 - LOSS OF TRACTION	Cargo Body Type: 02 - VAN/ENCLOSED BOX
Alcohol Test Given: NO	Abg Switch Stat:	Number of Axles: 5
Drug Test Given: 1 - NONE	Abg Deploy: 01 - NOT APPLICABLE	HazMat Involvement: 02 - NO
Total Occupants: 1	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Placard:
Vehicle Year: 1996	Ejection: 2 - NOT EJECTED	Placard #:
Vehicle Make: KENWORTH - KW	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:
Vehicle Model: T600	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Converter Dolly: 2
Vehicle Style: DS	Injury Status: 5 - UNINJURED	GVWR: 3 - 26,001 LBS OR MORE
Vehicle Color: BLUE - BLU	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1: 321.288(1)
Vehicle Config: 11 - TRUCK/TRAILER	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Vehicle Defect: 01 - NONE		Citation Charge 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 3:
Tow: 3 - DISABLED - OFFICER ARRANGED		Citation Charge 4:
Tow #: 16101		
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last: KOEHLMOOS	Bus Use:	Transported to:
First: LYLE		
Middle: EDWARD	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: GRANVILLE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51022		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr: 06 - LOST CONTROL
Age: 80	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$4,500.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt: NONE		
License Restrictions: B	Second Event: 11 - LOSS OF TRACTION	Carrier Name:
Speed Limit: 55		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Fourth Event:	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1	Most Harmful Event: 11 - LOSS OF TRACTION	Number of Axles:
Vehicle Year: 2012	Abg Switch Stat: 03 - NOT DEPLOYED	HazMat Involvement:
Vehicle Make: CHEVROLET - CHEV	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Vehicle Model: EQUINOX LTZ	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Style: 4W	Ejection: 2 - NOT EJECTED	HazMat Released?:
Vehicle Color: RED - RED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Defect: 01 - NONE	Injury Status: 5 - UNINJURED	Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Tow: 4 - NOT DISABLED - PRIVATELY ARRANGED	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Tow #: 4 - NOT DISABLED - PRIVATELY ARRANGED		Citation Charge 2:
Initial Trvl Dir: 01 - NORTH		Cit Chrg Code 3:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
		Cit Chrg Code 4:
		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 02 - WEATHER CONDITION
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 08 - BLOWING SNOW	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 03 - ICE/FROST	FRA No.:
	Horizontal Alignment:
Workzone Related: NO	Vertical Alignment:
Activity:	First Harmful Evt of Crash: 21 - JACKKNIFE
Location:	
Type:	
Workers Present:	

Narrative

Vehicle #1 was traveling north on Hwy 59. Vehicle #1 hit a slushy snow and ice patch that had accumulated due to the blowing snow. As a result vehicle #1 lost control of his truck causing it jack knife, blocking almost the whole road. Vehicle #2 was also traveling north bound. Vehicle #2 hit the same slush and ice mix as vehicle #1. Vehicle #2 attempted to avoid the semi that was blocking the road but was unable to do the road conditions and lack of room to pass the semi.

