

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	16-007117	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	12/07/16	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	07:15 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	DEPUTY STEVEN VANDERVEEN	Acc Loc City:		Distance 2:	"N/A"
Badge #:	71-9	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	12/07/2016	Closest City:	"N/A"	X-Coordinate:	00286441
Officer Notified:	07:20 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04775205
Officer Arrived:	07:23 Hrs.	Road,Street,HWay:	"N/A"	Location Literal:	"N/A"
Scene Investigated:	YES	Definable Location:	"N/A"	Description:	
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	CORCORAN	Bus Use:		Transported to:	
First:	NANCY	Drvtr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	ANNE	Traffic Controls:		Special Veh Func:	
City:	SHELDON	Point of Init Impact:		Emergency Status:	
State:	IA	Most Damaged Area:		Cont. Circum., Drvr:	
Zip:	51201-0000	Undrrid/Ovrid:		Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$12,000.00	Carrier Address:	
Gender:	Female	Ext of Damage:		Carrier City:	
Age:	63	First Event:		Carrier State:	
CDL:	NO	Second Event:		Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:	L	Most Harmful Event:		HazMat Involvement:	
License Restrictions:	NONE	Abg Switch Stat:		HazMat Placard:	
Speed Limit:		Abg Deploy:		Placard #:	
Seating Position:		Trapped:		HazMat Released?:	
Driver Condition:		Ejection:		Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:		GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:		Cit Chrg Code 1:	
Total Occupants:	1	Injury Status:		Citation Charge 1:	
Vehicle Year:	2014	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 2:	
Vehicle Make:	TOYOTA - TOYT	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Model:	AVA			Cit Chrg Code 3:	
Vehicle Style:	4D			Citation Charge 3:	
Vehicle Color:	MAKOOON, BURGUNDY (PIIRPI F) - MAR			Cit Chrg Code 4:	
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 4:	
Vehicle Defect:					
Vehicle Action:					
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:					
Vision Obscured:					

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash:
Type:	31 - ANIMAL
Workers Present:	

Narrative

Driver was southbound on Highway 59 and struck a buck deer on the north end of Primghar.