

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **17-000862**
 Date of Acc: **02/14/17**
 Time of Acc: **01:50** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY BRAD STEVENS**
 Badge #: **71-10**
 Report Date: **02/14/2017**
 Officer Notified: **01:52** Hrs.
 Officer Arrived: **21:05** Hrs.
 Scene Investigated: **YES**

Report to All Drivers: **YES**
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City: **"N/A"**
 Closest City: **"N/A"**
 Miles From City: **"N/A"**
 Road,Street,HWay: **"N/A"**
 Definable Location: **"N/A"**
 Milepost Number: **"N/A"**

At Intersection with: **"N/A"**
 Div HWay Trvl Dir: **"N/A"**
 Distance 1: **"N/A"**
 Direction 1: **"N/A"**
 Distance 2: **"N/A"**
 Direction 2: **"N/A"**
 X-Coordinate: **00291014**
 Y-Coordinate: **04755628**
 Location Literal: **B062/500TH ST**
 Description:

Unit 001

Driver Name - Last: DEVOS	Bus Use:	Transported to: N/A
First: JERAD		
Middle: LEE	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by: N/A
City: SUTHERLAND		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51058-0000		
Suffix:	Point of Init: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Impact:	
Age: 42	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL: YES	Undridd/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$10,457.00	
License Class: A	Ext of Damage: 4 - DISABLING DAMAGE	
License Endorsmnt: N - TANK	First Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Name: MEERDINK INC
License Restrictions: NONE		Carrier Address: 3676 IRONWOOD AVE
Speed Limit: 55	Second Event: 31 - ANIMAL	Carrier City: ORANGE CITY
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier State: IA
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Carrier Zip: 51041
Alcohol Test Given: NO		Cargo Body Type: 04 - CARGO TANK
Drug Test Given: 1 - NONE	Most Harmful Event: 31 - ANIMAL	Number of Axles: 6
Total Occupants: 1	Abg Switch Stat:	HazMat Involvement: 02 - NO
Vehicle Year: 2017	Abg Deploy: 01 - NOT APPLICABLE	HazMat Placard:
Vehicle Make: FREIGHTLINER - FRHT	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Model: CORONADO	Ejection: 1 - NOT APPLICABLE	HazMat Released?:
Vehicle Style: TRACTOR	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly: 2
Vehicle Color: WHITE - WHI	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR: 3 - 26,001 LBS OR MORE
Vehicle Config: 13 - TRACTOR/SEMI-TRAILER	Injury Status: 5 - UNINJURED	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Tow: 3 - DISABLED - OFFICER ARRANGED		Citation Charge 2:
Tow #: 17-00020		Cit Chrg Code 3:
Initial Trvl Dir: 04 - WEST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		Cit Chrg Code 4:
		Citation Charge 4:

Property Damage

Object Damaged: HORSES (2)	Company Owner Name:
Estimate of Damage: \$1,000.00	City: PAULLINA
Owner's Name - Last: HOUSTON	State: IA
First: MICHAEL	Zip Code: 51046
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 06 - ANIMAL IN ROADWAY
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
	Horizontal Alignment:
	Vertical Alignment:
Workzone Related: NO	First Harmful Evt of Crash: 31 - ANIMAL
Activity:	
Location:	
Type:	
Workers Present:	

Narrative

Unit 1 was westbound in the 6200 mile of 500th Street. Unit 1 was unable to avoid a group of horses that were loose and struck two of them.

Diagram

