INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Report to All Drivers: YES At Intersection with: "N/A" Case Number: Date of Acc: 04/21/17 Legal Intervention: NO Div HWay Trvl Dir: "N/A" Time of Acc: 18:30 Hrs. Private Property: NO Distance 1: "N/A" Name of Agency: O'BRIEN COUNTY SHERIFF'S County: **O'BRIEN - 71** Direction 1: "N/A" Acc Loc City: Distance 2: "N/A" Acc Dir From City: Officer: Direction 2: "N/A" "N/A" **BRACY DANIEL** Closest City: X-Coordinate: 00288432 "N/A" Badge #: Miles From City: Y-Coordinate: 71-6 "N/A" 04787994 L050/SORREL AVE

04/21/2017 Road, Street, HWay: "N/A" Location Literal Officer Notified: 19:23 Definable Location: "N/A" Description: Hrs. "N/A" Officer Arrived: 19:37 Hrs Milepost Number:

Scene Investigated: YES

Unit 001

Report Date:

Driver Name - Last: **CUADROS** Bus Use: Transported to First: ANA Middle Drvr Distractions: 99 - UNKNOWN Transported by: City: SIBLEY Special Veh Func: 01 - NO SPECIAL FUNCTION State: IΑ Traffic Controls: 01 - NO CONTROLS PRESENT Zip: 51249-1442 Suffix: 11 - FRONT DRIVER SIDE CORNER 01 - NOT APPLICABLE Point of Init **Emergency Status:** Gender: Female Impact: Age: 49 14 - UNDERCARRIAGE 06 - LOST CONTROL, 18 -Most Damaged Cont. Circum.. Drvr: NO CDI · SWERVED TO AVOID: Area: License State: VEHICLE, OBJECT, NON-IΑ Undrrid/Ovrid: 1 - NONE License Class: MOTORIST, OR ANIMAL IN С Rpr/Rplc Cost: \$8,000.00 ROADWAY License Endorsmnt NONE 5 - SEVERE, VEHICLE TOTALED Ext of Damage: License Restrictions: NONE First Event: 31 - ANIMAL Speed Limit: Carrier Name: 01 - 1ST ROW: LEFT Seating Position: Carrier Address: SIDE/MOTORCYCLE DRIVER 03 - RAN OFF ROAD, LEFT Second Event: Carrier City: 01 - APPARENTLY NORMAL **Driver Condition:** Carrier State: Alcohol Test Given: NO Carrier Zip: 47 - CULVERT/PIPE OPENING Third Event 1 - NONE Drug Test Given: Cargo Body Type: 01 - NOT APPLICABLE **Total Occupants:** 2 Fourth Event Vehicle Year: 2008 Number of Axles: Vehicle Make: HazMat Involvement: NISSAN - NISS HazMat Placard: Vehicle Model: ALT

47 - CULVERT/PIPE OPENING Most Harmful Placard #: Vehicle Style: Event: WHITE - WHI HazMat Released?: Vehicle Color:

Vehicle Config: 01 - PASSENGER CAR Abg Switch Stat: Converter Dolly:

03 - NOT DEPLOYED Abg Deploy: GVWR: 01 - NONE Vehicle Defect: Cit Chra Code 1:

321.288(1) 1 - NOT TRAPPED/APPLICABLE Trapped: Citation Charge 1: **FAILURE TO MAINTAIN** 01 - MOVEMENT ESSENTIALLY Vehicle Action: Eiection: 2 - NOT EJECTED CONTROL

STRAIGHT 01 - NOT EJECTED/NOT Ejection Path: Cit Chrg Code 2: **APPLICABLE** 3 - DISABLED - OFFICER Tow: Citation Charge 2: ARRANGED

99 - UNKNOWN Occpnt Protect: Tow #: Cit Chrg Code 3: Initial Trvl Dir: 03 - SOUTH Injury Status: Citation Charge 3: 5 - UNINJURED

01 - NOT OBSCURED Vision Obscured: Source of Trans: 01 - NOT TRANSPORTED Cit Chrg Code 4: 01 - NOT APPLICABLE Died at Scene: Citation Charge 4:

Accident Environment

First Harmful Event Loc: 04 - ROADSIDE Roadway Characteristics Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE) Environment: 06 - ANIMAL IN ROADWAY

Light Conditions: 01 - NONE APPARENT 1 - DAYLIGHT Roadway: 01 - CLEAR Weather Conditions:

Type of Road Junc/Feat: 05 - DRIVEWAY ACCESS (RELATED, NOT IN) Surface Conditions: 01 - DRY

FRA No.:

Horizontal Alignment: Workzone Related: Vertical Alignment: Activity:

Location: 47 - CULVERT/PIPE OPENING First Harmful Evt of Crash: Type:

Workers Present:

Narrative

VEH 1 WAS SOUTHBOUND ON SORREL AVE; WAS GOING TO TURN EAST INTO VANESS DAIRY DRIVEWAY; DRIVER CLAIMED THERE WAS A DEER ON THE ROAD; DRIVER PUT DOWN 106 FEET OF SKID MARKS ON DRY PAVEMENT BEFORE ENTERING THE LEFT DITCH; WHERE SHE THEN PUT DOWN 59 FEET OF SKIDS ON GRASS BEFORE IMPACTING A BOX CULVERT

4/21/2017 TT:29 Printed At: O'BRIEN COUNTY SHERIFF'S OFF 17-002358 Form #:

