INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

17-004283 Report to All Drivers: YES At Intersection with: Case Number: Date of Acc: 07/01/17 Legal Intervention: NO Div HWay Trvl Dir: "N/A" Time of Acc: 11:15 Hrs. Private Property: NO Distance 1: "N/A" Name of Agency: O'BRIEN COUNTY SHERIFF'S County: **O'BRIEN - 71** Direction 1: "N/A" Acc Loc City: Distance 2: "N/A" "N/A" Officer: Acc Dir From City: "N/A" Direction 2: **DEPUTY STEVEN VANDERVEEN** Closest City: X-Coordinate: 00288311 "N/A" Badge #: 71-9 Miles From City: "N/A" Y-Coordinate: 04783380 SORREL AVE Report Date: 07/01/2017 Road, Street, HWay: "N/A" Location Literal Officer Notified: 12:07 Definable Location: "N/A" Description: Hrs.

Unit 001

Officer Arrived:

Scene Investigated: YES

13:05

Hrs.

Driver Name - Last: PETERS Bus Use: Transported to: PRIMGHAR HOSPITAL First: CLINT Middle ANDREW Drvr Distractions: 02 - NOT DISTRACTED Transported by: PRIVATE VEHICLE **HARTLEY** City: 01 - NO SPECIAL FUNCTION Special Veh Func: State: IΑ Traffic Controls: 01 - NO CONTROLS PRESENT 51346-0000 Zip:

"N/A"

Suffix: 99 - UNKNOWN Point of Init **Emergency Status:** Gender: Male Impact:

Milepost Number:

Age: 13 - TOP OF VEHICLE 03 - EXCEEDED AUTHORIZED Most Damaged Cont. Circum., Drvr: NO CDL: SPEED, 06 - LOST CONTROL Area: License State: IΑ

01 - NOT APPLICABLE

Undrrid/Ovrid: 1 - NONE License Class: C \$2,000.00 Rpr/Rplc Cost: License Endorsmnt: NONE

5 - SEVERE, VEHICLE TOTALED Ext of Damage: License Restrictions: BY 03 - RAN OFF ROAD, LEFT First Event:

Speed Limit: 55 Carrier Name: 01 - 1ST ROW: LEFT Seating Position: Carrier Address: SIDE/MOTORCYCLE DRIVER 20 - OVERTURN/ROLLOVER Second Event:

Carrier City: 01 - APPARENTLY NORMAL Driver Condition: Carrier State: Alcohol Test Given: NO Carrier Zip: Third Event: 1 - NONE

Drug Test Given: Cargo Body Type: 01 - NOT APPLICABLE **Total Occupants:** 1 2002 Fourth Event:

Vehicle Year: Number of Axles: Vehicle Make: **CHRYSLER - CHRY** HazMat Involvement: Vehicle Model: TOW HazMat Placard:

20 - OVERTURN/ROLLOVER Most Harmful Vehicle Style: VN Placard #: Event: BLUE - BLU HazMat Released?: Vehicle Color:

04 - PASSENGER VAN (SEATS Vehicle Config: Abg Switch Stat: Converter Dolly: <9) 03 - NOT DEPLOYED

Abg Deploy: GVWR: 01 - NONE Vehicle Defect: 321.288(1)

Cit Chrg Code 1: 1 - NOT TRAPPED/APPLICABLE Trapped: Citation Charge 1:

FAILURE TO MAINTAIN 01 - MOVEMENT ESSENTIALLY 2 - NOT EJECTED 01 - NOT EJECTED/NOT Vehicle Action: Ejection: CONTROL **STRAIGHT**

Ejection Path: Cit Chrg Code 2: APPLICABLE 2 - DISABLED - PRIVATELY Tow: Citation Charge 2: ARRANGED 03 - SHOULDER AND LAP BELT

Occpnt Protect: Tow #: USED Cit Chrg Code 3:

Initial Trvl Dir: 01 - NORTH Injury Status: 2 - SUSPECTED Citation Charge 3: 01 - NOT OBSCURED Vision Obscured: SERIOUS/INCAPACITATING

05 - PARENT/SPOUSE/FRIEND Source of Trans: Cit Chrq Code 4:

01 - NOT APPLICABLE Died at Scene: Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY Roadway Characteristics Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE) **Environment**: 01 - NONE APPARENT 01 - NONE APPARENT **Light Conditions:** 1 - DAYLIGHT Roadway:

01 - CLEAR Weather Conditions: Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE

Surface Conditions: 01 - DRY

FRA No.: Horizontal Alignment: Vertical Alignment: Workzone Related: NO

Location: 20 - OVERTURN/ROLLOVER First Harmful Evt of Crash: Type:

Workers Present:

Narrative

Activity

Vehicle #1 was northbound on gravel road Sorrel Avenue. The driver admitted to driving too fast and lost control of the van. The van entered the west ditch and rolled over and then re-entered the roadway and landed on its wheels.

