INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	17-006050	Report to All Drivers:	Yes	At Intersection with:	
Date of Acc:	09/05/17	Legal Intervention:	No	Div HWay Trvl Dir:	
Time of Acc:	21:10 Hrs.	Private Property:	No	Distance 1:	
Name of Agency:	O'Brien County Sheriff's Off	County:	O'Brien - 71	Direction 1:	
		Acc Loc City:		Distance 2:	
Officer:	VANDERVEEN STEVEN	Acc Dir From City:		Direction 2:	
		Closest City:		X-Coordinate:	00283661
Badge #:	71-9	Miles From City:		Y-Coordinate:	04757503
Report Date:	09/05/2017	Road,Street,HWay:		Location Literal Description:	490TH ST
Officer Notified:	21:19 Hrs.	Definable Location:			
Officer Arrived:	21:33 Hrs.	Milepost Number:			
Scene Investigated:	Yes				

Unit 001

Driver Name - Last:	LANGE	Bus Use:		Transported to:	
First:	MICHELLE				
Middle:	MARIE	Drvr Distractions:	02 - Not distracted	Transported by:	
City:	PAULLINA				
State:	IA	Traffic Controls:	01 - No controls present	Special Veh Func:	01 - No special function
Zip:	51046-0000				
Suffix:		Point of Init Impact:	11 - Front Driver Side Corner	Emergency Status:	01 - Not applicable
Gender:	Female				
Age:	51	Most Damaged Area:	11 - Front Driver Side Corner	Cont. Circum., Drvr:	88 - No improper action
CDL:	No				
License State:	IA	Undrrid/Ovrid:	1 - None		
License Class:	C	Rpr/Rplc Cost:	$3,000.00		
License Endorsmnt:		Ext of Damage:	2 - Minor damage		
License Restrictions:	B	First Event:	31 - Animal		
Speed Limit:	50			Carrier Name:	
Seating Position:	01 - 1st row: left side/motorcycle driver	Second Event:		Carrier Address:	
				Carrier City:	
Driver Condition:	01 - Apparently normal			Carrier State:	
Alcohol Test Given:	NO	Third Event:		Carrier Zip:	
Drug Test Given:	1 - None			Cargo Body Type:	01 - Not applicable
Total Occupants:	1				
Vehicle Year:	2002	Fourth Event:		Number of Axles:	
Vehicle Make:	Ford - FORD			HazMat Involvement:	
Vehicle Model:	F25			HazMat Placard:	
Vehicle Style:	PK	Most Harmful Event:	31 - Animal	Placard #:	
Vehicle Color:	WHITE - WHI			HazMat Released?:	
Vehicle Config:	02 - Four-tire truck (pick-up)	Abg Switch Stat:		Converter Dolly:	
		Abg Deploy:	03 - Not deployed	GVWR:	
Vehicle Defect:	01 - None			Cit Chrg Code 1:	
		Trapped:	1 - Not trapped/applicable	Citation Charge 1:	
Vehicle Action:	01 - Movement essentially straight	Ejection:	2 - Not ejected		
		Ejection Path:	01 - Not ejected/not applicable	Cit Chrg Code 2:	
Tow:	1 - Driven away			Citation Charge 2:	
		Occpnt Protect:	03 - Shoulder and lap belt used		
Tow #:				Cit Chrg Code 3:	
Initial Trvl Dir:	04 - West	Injury Status:	5 - Uninjured	Citation Charge 3:	
Vision Obscured:	01 - Not obscured				
		Source of Trans:	01 - Not Transported	Cit Chrg Code 4:	
		Died at Scene:	01 - Not applicable	Citation Charge 4:	

Property Damage 001

Object Damaged:	STEER CALF	Company Owner Name:	
Estimate of Damage:	$700.00	City:	PAULLINA
Owner's Name - Last:	DAU	State:	IA
First:	CHAD	Zip Code:	51046
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - On roadway	Roadway Characteristics	
Manner of Crash/Collision:	01 - Non-collision (single vehicle)	Environment:	01 - None apparent
Light Conditions:	5 - Dark, roadway not lighted	Roadway:	01 - None apparent
Weather Conditions:	01 - Clear		
		Type of Road Junc/Feat:	01 - Non-junction/no special feature
Surface Conditions:	01 - Dry		
		FRA No.:	
		Horizontal Alignment:	
Workzone Related:	No	Vertical Alignment:	
Activity:			
Location:			
Type:		First Harmful Evt of Crash:	31 - Animal
Workers Present:			

Narrative

VEHICLE #1 WAS WESTBOUND ON GRAVEL ROAD 490TH STREET EAST OF L-48. THERE WAS A BLACK WHITE FACE STEER ON THE ROAD. VEHICLE #1

STRUCK AND KILLED THE STEER.

Diagram