

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: S17-007373	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 11/05/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 17:59 Hrs.	Private Property: No	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: VANMEETEREN KEVEN	Acc Loc City:	Distance 2:
Badge #: 71-7	Acc Dir From City:	Direction 2:
Report Date: 11/05/2017	Closest City:	X-Coordinate: 00271978
Officer Notified: 18:01 Hrs.	Miles From City:	Y-Coordinate: 04774383
Officer Arrived: 18:21 Hrs.	Road, Street, HWay:	Location Literal: L036/NETTLE AVE
Scene Investigated: Yes	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: EGESDAL	Bus Use:	Transported to:
First: AMBER		
Middle: MARIE	Drv Distractions: 02 - Not distracted	Transported by:
City: LAKE PARK		
State: IA	Traffic Controls:	Special Veh Func:
Zip: 51347-0000		
Suffix:	Point of Init Impact:	Emergency Status:
Gender: Female		
Age: 33	Most Damaged Area:	Cont. Circum., Drvr: 88 - No improper action
CDL: No	Undrrid/Ovrid:	
License State: IA	Rpr/Rplc Cost: \$4,000.00	
License Class: C	Ext of Damage:	
License Endorsmnt:	First Event:	Carrier Name:
License Restrictions: B		Carrier Address:
Speed Limit:		Carrier City:
Seating Position:	Second Event:	Carrier State:
		Carrier Zip:
Driver Condition:	Third Event:	Cargo Body Type: 01 - Not applicable
Alcohol Test Given: NO		
Drug Test Given: 1 - None	Fourth Event:	Number of Axles:
Total Occupants: 01		HazMat Involvement:
Vehicle Year: 2012	Most Harmful Event:	HazMat Placard:
Vehicle Make: Hyundai - HYUN		Placard #:
Vehicle Model: ELN	Abg Switch Stat:	HazMat Released?:
Vehicle Style: 4D	Abg Deploy:	Converter Dolly:
Vehicle Color: WHITE - WHI		GVWR:
Vehicle Config: 01 - Passenger car	Trapped:	Cit Chrg Code 1:
Vehicle Defect:	Ejection:	Citation Charge 1:
Vehicle Action:	Ejection Path:	
Tow: 1 - Driven away	Occpnt Protect:	Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir:	Injury Status:	Cit Chrg Code 3:
Vision Obscured:		Citation Charge 3:
	Source of Trans: 01 - Not Transported	Cit Chrg Code 4:
	Died at Scene: 01 - Not applicable	Citation Charge 4:

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
	Type of Road Junc/Feat:
Surface Conditions:	
	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 31 - Animal
Workers Present:	

Narrative

UNIT 1 SOUTHBOUND IN THE 3800 MILE OF NETTLE AVE (L36) WHEN A DEER CAME OUT OF THE EAST DITCH AND UNIT 1 STRUCK THE DEER IN THE ROADWAY. NO INJURIES REPORTED TO THE DRIVER AND THE VEHICLE WAS ABLE TO BE DRIVEN AWAY FROM THE SCENE.

NOT TO SCALE

NETTLE AVE (L36)

