

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-008082	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 12/12/17	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 15:30 Hrs.	Private Property: Yes	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: VANDERVEEN STEVEN	Acc Loc City:	Distance 2:
Badge #: 71-9	Acc Dir From City:	Direction 2:
Report Date: 12/12/2017	Closest City:	X-Coordinate: 00304360
Officer Notified: 14:44 Hrs.	Miles From City:	Y-Coordinate: 04782886
Officer Arrived: 14:51 Hrs.	Road, Street, HWay:	Location Literal: OFF ROADWAY/ROADWAY NOT FOUND
Scene Investigated: Yes	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: RUHLAND	Bus Use:	Transported to:
First: ROGER		
Middle: HENRY	Drvr Distractions: 99 - Unknown	Transported by:
City: LE MARS		
State: IA	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
Zip: 51031-0000		
Suffix:	Point of Init Impact: 05 - Rear Passenger Side Corner	Emergency Status: 01 - Not applicable
Gender: Male	Most Damaged Area: 15 - Non-collision/no damage	Cont. Circum., Drvr: 19 - Starting or backing improperly
Age: 61	Undrrid/Ovrid: 1 - None	
CDL: Yes	Rpr/Rplc Cost: \$0.00	
License State: IA	Ext of Damage: 1 - None	
License Class: A	First Event: 35 - Parked motor vehicle	Carrier Name:
License Endorsmnt: X - Hazmat & Tank		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit:	Third Event:	Carrier State:
Seating Position: 01 - 1st row: left side/motorcycle driver	Fourth Event:	Carrier Zip:
Driver Condition: 01 - Apparently normal		Cargo Body Type: 05 - Flatbed
Alcohol Test Given: NO	Most Harmful Event: 35 - Parked motor vehicle	Number of Axles:
Drug Test Given: 1 - None	Abg Switch Stat:	HazMat Involvement:
Total Occupants: 1	Abg Deploy: 03 - Not deployed	HazMat Placard:
Vehicle Year: 2014	Trapped: 1 - Not trapped/applicable	Placard #:
Vehicle Make: RAM - RAM	Ejection: 2 - Not ejected	HazMat Released?:
Vehicle Model: RTR	Ejection Path: 01 - Not ejected/not applicable	Converter Dolly:
Vehicle Style: PK	Occpnt Protect: 03 - Shoulder and lap belt used	GVWR:
Vehicle Color: BLACK - BLK	Injury Status: 5 - Uninjured	Cit Chrg Code 1:
Vehicle Config: 07 - Single-unit truck (2-axle, 6-tire)	Source of Trans: 01 - Not Transported	Citation Charge 1:
Vehicle Defect: 01 - None	Died at Scene: 01 - Not applicable	Cit Chrg Code 2:
Vehicle Action: 09 - Backing		Citation Charge 2:
Tow: 1 - Driven away		Cit Chrg Code 3:
Tow #:		Citation Charge 3:
Initial Trvl Dir: 02 - East		Cit Chrg Code 4:
Vision Obscured: 01 - Not obscured		Citation Charge 4:

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - Not applicable/no driver	Transported by:
City:		
State:	Traffic Controls:	Special Veh Func:
Zip:		
Suffix:	Point of Init 04 - Rear Passenger Side	Emergency Status:
Gender:	Impact:	
Age:	Most Damaged 04 - Rear Passenger Side	Cont. Circum., Drvr: 88 - No improper action
CDL:	Area:	
License State:	Undrrid/Ovrid: 1 - None	
License Class:	Rpr/Rplc Cost: \$2,000.00	
License Endorsmnt:	Ext of Damage: 2 - Minor damage	
License Restrictions:	First Event:	Carrier Name:
Speed Limit:		Carrier Address:
Seating Position:		Carrier City:
	Second Event:	Carrier State:
Driver Condition:		Carrier Zip:
Alcohol Test Given:	Third Event:	Cargo Body Type: 01 - Not applicable
Drug Test Given:		
Total Occupants: 0	Fourth Event:	Number of Axles:
Vehicle Year: 2013		HazMat Involvement:
Vehicle Make: Chevrolet - CHEV	Most Harmful Event:	HazMat Placard:
Vehicle Model: SLV		Placard #:
Vehicle Style: PK	Abg Switch Stat:	HazMat Released?:
Vehicle Color: RED - RED	Abg Deploy:	Converter Dolly:
Vehicle Config: 02 - Four-tire truck (pick-up)		GVWR:
	Trapped:	Cit Chrg Code 1:
Vehicle Defect:	Ejection:	Citation Charge 1:
Vehicle Action: 12 - Legally Parked	Ejection Path:	
	Occpnt Protect:	Cit Chrg Code 2:
Tow:		Citation Charge 2:
Tow #:	Injury Status:	Cit Chrg Code 3:
Initial Trvl Dir:		Citation Charge 3:
Vision Obscured:	Source of Trans:	Cit Chrg Code 4:
	Died at Scene:	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 98 - Other (explain in narrative)	Roadway Characteristics
Manner of Crash/Collision: 09 - Rear to side	Environment: 01 - None apparent
Light Conditions: 1 - Daylight	Roadway: 01 - None apparent
Weather Conditions: 01 - Clear	
	Type of Road Junc/Feat: 96 - Other non-intersection (explain in narrative)
Surface Conditions: 01 - Dry	
	FRA No.:
Workzone Related: No	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - Parked motor vehicle
Workers Present:	

Narrative

Vehicle #1 was at a hog building site located by 3272 Yew Avenue Hartley, Ia. The driver was backing up his truck on the yard at this hog building site and backed into the side of another pickup that was parked at the building site.

