

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

|                                                     |                                   |                                           |
|-----------------------------------------------------|-----------------------------------|-------------------------------------------|
| Case Number: <b>S17-008283</b>                      | Report to All Drivers: <b>Yes</b> | At Intersection with:                     |
| Date of Acc: <b>12/20/17</b>                        | Legal Intervention: <b>No</b>     | Div HWay Trvl Dir:                        |
| Time of Acc: <b>19:23 Hrs.</b>                      | Private Property: <b>No</b>       | Distance 1:                               |
| Name of Agency: <b>O'Brien County Sheriff's Off</b> | County: <b>O'Brien - 71</b>       | Direction 1:                              |
| Officer: <b>DEPUTY KEVEN VANMEETEREN</b>            | Acc Loc City:                     | Distance 2:                               |
| Badge #: <b>71-7</b>                                | Acc Dir From City:                | Direction 2:                              |
| Report Date: <b>12/20/2017</b>                      | Closest City:                     | X-Coordinate: <b>00281117</b>             |
| Officer Notified: <b>19:23 Hrs.</b>                 | Miles From City:                  | Y-Coordinate: <b>04758742</b>             |
| Officer Arrived: <b>19:43 Hrs.</b>                  | Road, Street, HWay:               | Location Literal: <b>L048/REDWING AVE</b> |
| Scene Investigated: <b>Yes</b>                      | Definable Location:               | Description:                              |
|                                                     | Milepost Number:                  |                                           |

**Unit 001**

|                                                   |                                               |                                                     |
|---------------------------------------------------|-----------------------------------------------|-----------------------------------------------------|
| Driver Name - Last: <b>PEDERSEN</b>               | Bus Use:                                      | Transported to:                                     |
| First: <b>LONDON</b>                              |                                               |                                                     |
| Middle: <b>CHRISTOPHER</b>                        | Drvr Distractions: <b>02 - Not distracted</b> | Transported by:                                     |
| City: <b>MERIDEN</b>                              |                                               |                                                     |
| State: <b>IA</b>                                  | Traffic Controls:                             | Special Veh Func:                                   |
| Zip: <b>51037-0000</b>                            |                                               |                                                     |
| Suffix:                                           | Point of Init Impact:                         | Emergency Status:                                   |
| Gender: <b>Male</b>                               |                                               |                                                     |
| Age: <b>33</b>                                    | Most Damaged Area:                            | Cont. Circum., Drvr: <b>88 - No improper action</b> |
| CDL: <b>No</b>                                    | Undrrid/Ovrid:                                |                                                     |
| License State: <b>IA</b>                          | Rpr/Rplc Cost: <b>\$5,000.00</b>              |                                                     |
| License Class: <b>C</b>                           | Ext of Damage:                                |                                                     |
| License Endorsmnt:                                | First Event:                                  | Carrier Name:                                       |
| License Restrictions:                             |                                               | Carrier Address:                                    |
| Speed Limit:                                      |                                               | Carrier City:                                       |
| Seating Position:                                 | Second Event:                                 | Carrier State:                                      |
|                                                   |                                               | Carrier Zip:                                        |
| Driver Condition:                                 | Third Event:                                  | Cargo Body Type: <b>01 - Not applicable</b>         |
| Alcohol Test Given: <b>NO</b>                     |                                               |                                                     |
| Drug Test Given: <b>1 - None</b>                  | Fourth Event:                                 | Number of Axles:                                    |
| Total Occupants: <b>01</b>                        |                                               | HazMat Involvement:                                 |
| Vehicle Year: <b>2011</b>                         | Most Harmful Event:                           | HazMat Placard:                                     |
| Vehicle Make: <b>Kingham - KNGH</b>               |                                               | Placard #:                                          |
| Vehicle Model: <b>SOR</b>                         | Abg Switch Stat:                              | HazMat Released?:                                   |
| Vehicle Style: <b>4D</b>                          | Abg Deploy:                                   | Converter Dolly:                                    |
| Vehicle Color: <b>RED - RED</b>                   |                                               | GVWR:                                               |
| Vehicle Config: <b>03 - Sport utility vehicle</b> | Trapped:                                      | Cit Chrg Code 1:                                    |
| Vehicle Defect:                                   | Ejection:                                     | Citation Charge 1:                                  |
| Vehicle Action:                                   | Ejection Path:                                |                                                     |
| Tow: <b>3 - Disabled - officer arranged</b>       | Occpnt Protect:                               | Cit Chrg Code 2:                                    |
| Tow #: <b>17-0127</b>                             |                                               | Citation Charge 2:                                  |
| Initial Trvl Dir:                                 | Injury Status:                                | Cit Chrg Code 3:                                    |
| Vision Obscured:                                  |                                               | Citation Charge 3:                                  |
|                                                   | Source of Trans: <b>01 - Not Transported</b>  | Cit Chrg Code 4:                                    |
|                                                   | Died at Scene: <b>01 - Not applicable</b>     | Citation Charge 4:                                  |

**Accident Environment**

|                            |                                                |
|----------------------------|------------------------------------------------|
| First Harmful Event Loc:   | <b>Roadway Characteristics</b>                 |
| Manner of Crash/Collision: | Environment:                                   |
| Light Conditions:          | Roadway:                                       |
| Weather Conditions:        |                                                |
|                            | Type of Road Junc/Feat:                        |
| Surface Conditions:        |                                                |
|                            | FRA No.:                                       |
| Workzone Related:          | Horizontal Alignment:                          |
| Activity:                  | Vertical Alignment:                            |
| Location:                  | First Harmful Evt of Crash: <b>31 - Animal</b> |
| Type:                      |                                                |
| Workers Present:           |                                                |

**Narrative**

UNIT 1 SOUTHBOUND ON REDWING AVE (L48) AND STRUCK A DEER IN THE ROADWAY.



Diagram

