

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: S18-000671	Report to All Drivers: Yes	At Intersection with:
Date of Acc: 02/05/18	Legal Intervention: No	Div HWay Trvl Dir:
Time of Acc: 09:13 Hrs.	Private Property: No	Distance 1:
Name of Agency: O'Brien County Sheriff's Off	County: O'Brien - 71	Direction 1:
Officer: VANMEETEREN KEVEN	Acc Loc City:	Distance 2:
Badge #: 71-7	Acc Dir From City:	Direction 2:
Report Date: 02/05/2018	Closest City:	X-Coordinate: 00271961
Officer Notified: 09:14 Hrs.	Miles From City:	Y-Coordinate: 04773713
Officer Arrived: 09:30 Hrs.	Road, Street, HWay:	Location Literal: 3916 NETTLE AVE
Scene Investigated: Yes	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: BLAUWET	Bus Use:	Transported to: N/A
First: DARREN	Drvr Distractions: 02 - Not distracted	Transported by: N/A
Middle: DANIEL	Traffic Controls: 01 - No controls present	Special Veh Func: 01 - No special function
City: LARCHWOOD	Point of Init Impact: 11 - Front Driver Side Corner	Emergency Status: 01 - Not applicable
State: IA	Most Damaged Area: 11 - Front Driver Side Corner	Cont. Circum., Drvr: 06 - Lost control
Zip: 51241-0000	Undrrid/Ovrid: 1 - None	Carrier Name:
Suffix:	Rpr/Rplc Cost: \$5,000.00	Carrier Address:
Gender: Male	Ext of Damage: 5 - Severe, vehicle totaled	Carrier City:
Age: 19	First Event: 01 - Ran off road, right	Carrier State:
CDL: No	Second Event: 06 - Evasive action (swerve, panic braking, avoidance)	Carrier Zip:
License State: IA	Third Event: 20 - Overturn/rollover	Cargo Body Type: 01 - Not applicable
License Class: C	Fourth Event:	Number of Axles:
License Endorsmnt: B	Most Harmful Event: 01 - Ran off road, right	HazMat Involvement:
License Restrictions: B	Abg Switch Stat:	HazMat Placard:
Speed Limit: 55	Abg Deploy: 03 - Not deployed	Placard #:
Seating Position: 01 - 1st row: left side/motorcycle driver	Trapped: 1 - Not trapped/applicable	HazMat Released?:
Driver Condition: 01 - Apparently normal	Ejection: 2 - Not ejected	Converter Dolly:
Alcohol Test Given: NO	Ejection Path: 01 - Not ejected/not applicable	GVWR:
Drug Test Given: 1 - None	Occpnt Protect: 03 - Shoulder and lap belt used	Cit Chrg Code 1:
Total Occupants: 02	Injury Status: 5 - Uninjured	Citation Charge 1:
Vehicle Year: 2006	Source of Trans: 01 - Not Transported	Cit Chrg Code 2:
Vehicle Make: Chevrolet - CHEV	Died at Scene: 01 - Not applicable	Citation Charge 2:
Vehicle Model: MALIBU LTZ		Cit Chrg Code 3:
Vehicle Style:		Citation Charge 3:
Vehicle Color: SILVER - SIL		Cit Chrg Code 4:
Vehicle Config: 01 - Passenger car		Citation Charge 4:
Vehicle Defect: 01 - None		
Vehicle Action: 01 - Movement essentially straight		
Tow: 3 - Disabled - officer arranged		
Tow #: 18-0009		
Initial Trvl Dir: 03 - South		
Vision Obscured: 14 - Blowing snow		

Accident Environment

First Harmful Event Loc: 02 - Shoulder	Roadway Characteristics
Manner of Crash/Collision: 01 - Non-collision (single vehicle)	Environment: 02 - Weather condition
Light Conditions: 1 - Daylight	Roadway: 02 - Surface condition (e.g., wet, icy)
Weather Conditions: 07 - Snow, 08 - Blowing snow	Type of Road Junc/Feat: 01 - Non-junction/no special feature
Surface Conditions: 04 - Snow	FRA No.:
Workzone Related: No	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 20 - Overturn/rollover
Type:	
Workers Present:	

Injured Person 001

Name - Last: **BLANKESPOOR**
First: **TATE**
Middle: **BENJAMIN**
Suffix:
City: **INWOOD**
State: **IA**
Zip Code: **51240**
Age: **19**
Sex: **Male**
Unit No.: **01**
Seating Position: **03 - 1st row: right side**
Occupant Protection: **03 - Shoulder and lap belt used**

Airbag Deployment: **03 - Not deployed**
Airbag Switch Status:
Trapped: **1 - Not trapped/applicable**
Injury Status: **3 - Suspected minor/non-incapacitating**
Ejection: **2 - Not ejected**
Ejection Path: **01 - Not ejected/not applicable**
Alcohol Test Given:
Drug Test Given:
Source of Transport: **01 - Not Transported**
Died at Scene/Enroute: **01 - Not applicable**
Transported to: **N/A**
Transported by: **N/A**

Narrative

UNIT 1 SOUTHBOUND ON NETTLE AVE (L36) AND DUE TO SNOW COVERED ROADWAY THE DRIVER DROPPED THE SIDE OF THE VEHICLE OFF ONTO THE WEST SHOULDER AND WENT INTO THE WEST DITCH WHERE THE VEHICLE ROLLED AND LANDED ON THE ROOF. DRIVER UNINJURED AND PASSENGER HAD SMALL CUT ON HAND, MEDICAL TREATMENT DENIED.

Diagram

NTS



