

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>18-003100</b>	Report to All Drivers: <b>Yes</b>	At Intersection with:
Date of Acc: <b>05/24/18</b>	Legal Intervention: <b>No</b>	Div HWay Trvl Dir:
Time of Acc: <b>08:28</b> Hrs.	Private Property: <b>No</b>	Distance 1:
Name of Agency: <b>O'Brien County Sheriff's Off</b>	County: <b>O'Brien - 71</b>	Direction 1:
Officer: <b>DEPUTY STEVEN VANDERVEEN</b>	Acc Loc City:	Distance 2:
Badge #: <b>71-9</b>	Acc Dir From City:	Direction 2:
Report Date: <b>05/24/2018</b>	Closest City:	X-Coordinate: <b>00298706</b>
Officer Notified: <b>08:23</b> Hrs.	Miles From City:	Y-Coordinate: <b>04784317</b>
Officer Arrived: <b>08:23</b> Hrs.	Road, Street, HWay:	Location Literal: <b>US 18/3RD ST NW AND US</b>
Scene Investigated: <b>Yes</b>	Definable Location:	Description: <b>18/3RD ST NE AND CENTRAL</b>
	Milepost Number:	<b>AVE AND WALNUT AVE</b>

**Unit 001**

Driver Name - Last: <b>GUINN</b>	Bus Use:	Transported to:
First: <b>NATHAN</b>	Drvr Distractions: <b>02 - Not distracted</b>	Transported by:
Middle: <b>EUGENE</b>	Traffic Controls: <b>01 - No controls present</b>	Special Veh Func: <b>01 - No special function</b>
City: <b>SPENCER</b>	Point of Init Impact: <b>12 - Front Middle</b>	Emergency Status: <b>01 - Not applicable</b>
State: <b>IA</b>	Most Damaged Area: <b>12 - Front Middle</b>	Cont. Circum., Drvr: <b>07 - Followed too close</b>
Zip: <b>51301-0000</b>	Undrrid/Ovrid: <b>1 - None</b>	Carrier Name:
Suffix:	Rpr/Rplc Cost: <b>\$9,000.00</b>	Carrier Address:
Gender: <b>Male</b>	Ext of Damage: <b>4 - Disabling damage</b>	Carrier City:
Age: <b>38</b>	First Event: <b>33 - Vehicle in traffic</b>	Carrier State:
CDL: <b>No</b>	Second Event:	Carrier Zip:
License State: <b>IA</b>	Third Event:	Cargo Body Type: <b>01 - Not applicable</b>
License Class: <b>C</b>	Fourth Event:	Number of Axles:
License Endorsmnt: <b>L</b>	Most Harmful Event: <b>33 - Vehicle in traffic</b>	HazMat Involvement:
License Restrictions:	Abg Switch Stat:	HazMat Placard:
Speed Limit: <b>35</b>	Abg Deploy: <b>03 - Not deployed</b>	Placard #:
Seating Position: <b>01 - 1st row: left side/motorcycle driver</b>	Trapped: <b>1 - Not trapped/applicable</b>	HazMat Released?:
Driver Condition: <b>01 - Apparently normal</b>	Ejection: <b>1 - Not applicable</b>	Converter Dolly:
Alcohol Test Given: <b>NO</b>	Ejection Path: <b>01 - Not ejected/not applicable</b>	GVWR:
Drug Test Given: <b>1 - None</b>	Occpnt Protect: <b>03 - Shoulder and lap belt used</b>	Cit Chrg Code 1: <b>321.307</b>
Total Occupants: <b>1</b>	Injury Status: <b>5 - Uninjured</b>	Citation Charge 1: <b>FOLLOWING TOO CLOSE</b>
Vehicle Year: <b>2015</b>	Source of Trans: <b>01 - Not Transported</b>	Cit Chrg Code 2:
Vehicle Make: <b>Chrysler - CHRY</b>	Died at Scene: <b>01 - Not applicable</b>	Citation Charge 2:
Vehicle Model: <b>20S</b>		Cit Chrg Code 3:
Vehicle Style: <b>4D</b>		Citation Charge 3:
Vehicle Color: <b>MAROON, BURGUNDY (PURPL</b>		Cit Chrg Code 4:
Vehicle Config: <b>01 - Passenger car</b>		Citation Charge 4:
Vehicle Defect: <b>01 - None</b>		
Vehicle Action: <b>01 - Movement essentially straight</b>		
Tow: <b>2 - Disabled - privately arranged</b>		
Tow #: <b>04 - West</b>		
Initial Trvl Dir: <b>01 - Not obscured</b>		
Vision Obscured:		

**Unit 002**

Driver Name - Last: <b>SCHMITH</b>	Bus Use:	Transported to:
First: <b>KARLEA</b>		
Middle: <b>MICHELLE</b>	Drvr Distractions: <b>02 - Not distracted</b>	Transported by:
City: <b>HARTLEY</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - No controls present</b>	Special Veh Func: <b>01 - No special function</b>
Zip: <b>51346-0000</b>		
Suffix:	Point of Init Impact: <b>06 - Rear Middle</b>	Emergency Status: <b>01 - Not applicable</b>
Gender: <b>Female</b>	Most Damaged Area: <b>06 - Rear Middle</b>	Cont. Circum., Drvr: <b>88 - No improper action</b>
Age: <b>16</b>	Undrrid/Ovrid: <b>1 - None</b>	
CDL: <b>No</b>	Rpr/Rplc Cost: <b>\$2,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>5 - Severe, vehicle totaled</b>	
License Class: <b>C</b>	First Event: <b>33 - Vehicle in traffic</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: <b>BY</b>		Carrier City:
Speed Limit: <b>35</b>	Second Event:	Carrier State:
Seating Position: <b>01 - 1st row: left side/motorcycle driver</b>		Carrier Zip:
Driver Condition: <b>01 - Apparently normal</b>	Third Event:	Cargo Body Type: <b>01 - Not applicable</b>
Alcohol Test Given: <b>NO</b>		
Drug Test Given: <b>1 - None</b>	Fourth Event:	Number of Axles:
Total Occupants: <b>1</b>		HazMat Involvement:
Vehicle Year: <b>2001</b>	Most Harmful Event: <b>33 - Vehicle in traffic</b>	HazMat Placard:
Vehicle Make: <b>Mercury - MERC</b>		Placard #:
Vehicle Model: <b>SAB</b>	Abg Switch Stat:	HazMat Released?:
Vehicle Style: <b>4D</b>	Abg Deploy: <b>03 - Not deployed</b>	Converter Dolly:
Vehicle Color: <b>RED - RED</b>		GVWR:
Vehicle Config: <b>01 - Passenger car</b>	Trapped: <b>1 - Not trapped/applicable</b>	Cit Chrg Code 1:
Vehicle Defect: <b>01 - None</b>	Ejection: <b>2 - Not ejected</b>	Citation Charge 1:
Vehicle Action: <b>02 - Turning left</b>	Ejection Path: <b>01 - Not ejected/not applicable</b>	Cit Chrg Code 2:
Tow: <b>2 - Disabled - privately arranged</b>	Occpnt Protect: <b>03 - Shoulder and lap belt used</b>	Citation Charge 2:
Tow #:		Cit Chrg Code 3:
Initial Trvl Dir: <b>04 - West</b>	Injury Status: <b>5 - Uninjured</b>	Citation Charge 3:
Vision Obscured: <b>01 - Not obscured</b>	Source of Trans: <b>01 - Not Transported</b>	Cit Chrg Code 4:
	Died at Scene: <b>01 - Not applicable</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>01 - On roadway</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>03 - Rear end (front to rear)</b>	Environment: <b>01 - None apparent</b>
Light Conditions: <b>1 - Daylight</b>	Roadway: <b>01 - None apparent</b>
Weather Conditions: <b>01 - Clear</b>	
	Type of Road Junc/Feat: <b>12 - Four-way intersection</b>
Surface Conditions: <b>01 - Dry</b>	
	FRA No.:
Workzone Related: <b>No</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>33 - Vehicle in traffic</b>
Type:	
Workers Present:	

**Narrative**

VEHICLE#1 WAS WESTBOUND ON FOUR LANE HIGHWAY 18 IN THE CITY LIMITS OF HARTLEY. VEHICLE #1 HAD BEEN IN THE RIGHT LANE TO PASS A VEHICLE AND THEN MOVED BACK INTO THE LEFT WESTBOUND LANE. VEHICLE #2 WAS WESTBOUND ON HIGHWAY 18 IN THE LEFT WESTBOUND LANE AND WAS ABOUT TO TURN LEFT. VEHICLE #1 DID NOT SEE VEHICLE #2 IN TIME AND RAN INTO THE BACK OF VEHICLE #2



