

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>S18-003274</b>	Report to All Drivers: <b>Yes</b>	At Intersection with:
Date of Acc: <b>05/29/18</b>	Legal Intervention: <b>No</b>	Div HWay Trvl Dir:
Time of Acc: <b>22:20</b> Hrs.	Private Property: <b>No</b>	Distance 1:
Name of Agency: <b>O'Brien County Sheriff's Off</b>	County: <b>O'Brien - 71</b>	Direction 1:
Officer: <b>DEPUTY KEVEN VANMEETEREN</b>	Acc Loc City:	Distance 2:
Badge #: <b>71-7</b>	Acc Dir From City:	Direction 2:
Report Date: <b>05/29/2018</b>	Closest City:	X-Coordinate: <b>00303295</b>
Officer Notified: <b>22:20</b> Hrs.	Miles From City:	Y-Coordinate: <b>04771257</b>
Officer Arrived: <b>22:29</b> Hrs.	Road, Street, HWay:	Location Literal: <b>B040/400TH ST</b>
Scene Investigated: <b>Yes</b>	Definable Location:	Description:
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>JOHNSON</b>	Bus Use:	Transported to:
First: <b>ALIVIA</b>		
Middle: <b>MIRANDA</b>	Drvr Distractions: <b>02 - Not distracted</b>	Transported by:
City: <b>ROYAL</b>		
State: <b>IA</b>	Traffic Controls:	Special Veh Func:
Zip: <b>51357-0000</b>		
Suffix:	Point of Init Impact:	Emergency Status:
Gender: <b>Female</b>		
Age: <b>24</b>	Most Damaged Area:	Cont. Circum., Drvr: <b>88 - No improper action</b>
CDL: <b>No</b>	Undrrid/Ovrid:	
License State: <b>IA</b>	Rpr/Rplc Cost: <b>\$3,000.00</b>	
License Class: <b>C</b>	Ext of Damage:	
License Endorsmnt:	First Event:	Carrier Name:
License Restrictions: <b>B</b>		Carrier Address:
Speed Limit:		Carrier City:
Seating Position:	Second Event:	Carrier State:
		Carrier Zip:
Driver Condition:	Third Event:	Cargo Body Type: <b>01 - Not applicable</b>
Alcohol Test Given: <b>NO</b>		
Drug Test Given: <b>1 - None</b>	Fourth Event:	Number of Axles:
Total Occupants: <b>01</b>		HazMat Involvement:
Vehicle Year: <b>2005</b>	Most Harmful Event:	HazMat Placard:
Vehicle Make: <b>Dorsey - DORS</b>		Placard #:
Vehicle Model: <b>DUR</b>	Abg Switch Stat:	HazMat Released?:
Vehicle Style: <b>SW</b>	Abg Deploy:	Converter Dolly:
Vehicle Color: <b>MAROON, BURGUNDY (PURPL</b>		GVWR:
Vehicle Config: <b>03 - Sport utility vehicle</b>	Trapped:	Cit Chrg Code 1:
Vehicle Defect:	Ejection:	Citation Charge 1:
Vehicle Action:	Ejection Path:	
Tow: <b>1 - Driven away</b>	Occpnt Protect:	Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir:	Injury Status:	Cit Chrg Code 3:
Vision Obscured:		Citation Charge 3:
	Source of Trans: <b>01 - Not Transported</b>	Cit Chrg Code 4:
	Died at Scene: <b>01 - Not applicable</b>	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	
Surface Conditions:	Type of Road Junc/Feat:
Workzone Related:	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: <b>31 - Animal</b>
Workers Present:	

**Narrative**

UNIT 1 EASTBOUND ON 400TH ST (B40) AND STRUCK A DEER THAT CAME OUT OF THE DITCH.





6950 400TH ST

