

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-003854	Report to All Drivers:	At Intersection with:
Date of Acc: 06/22/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 04:35 Hrs.	Private Property: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	County: O'BRIEN - 71	Direction 1:
Officer: DEPUTY STEVEN VANDERVEEN	Acc Loc City:	Distance 2:
Badge #: 71-9	Acc Dir From City:	Direction 2:
Report Date: 06/22/2018	Closest City:	X-Coordinate: 00298257
Officer Notified: 04:44 Hrs.	Miles From City:	Y-Coordinate: 04778017
Officer Arrived: 04:54 Hrs.	Road, Street, HWay:	Location Literal: B024/360TH ST
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: ZELINSKY	Bus Use:	Transported to:
First: BRADLEY		
Middle: JAMES	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SPENCER		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51301		
Suffix:	Point of Init 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Impact:	
Age: 59	Most Damaged 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL: NO	Area:	
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$4,500.00	
License Endorsmnt:	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Restrictions: B	First Event: 31 - ANIMAL	
Speed Limit: 55		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Address:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier City:
Alcohol Test Given: NO	Third Event:	Carrier State:
Drug Test Given: 1 - NONE		Carrier Zip:
Total Occupants: 1	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Vehicle Year: 2014		Number of Axles:
Vehicle Make: RAM - RAM	Most Harmful 31 - ANIMAL	HazMat Involvement:
Vehicle Model: RVA	Event:	HazMat Placard:
Vehicle Style: VN	Abg Switch Stat:	Placard #:
Vehicle Color: WHITE - WHI	Abg Deploy: 03 - NOT DEPLOYED	HazMat Released?:
Vehicle Config: 04 - PASSENGER VAN (SEATS <9)	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Defect: 01 - NONE	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Tow: 1 - DRIVEN AWAY	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Tow #:		Cit Chrg Code 2:
Initial Trvl Dir: 04 - WEST		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED	5 - UNINJURED	Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Property Damage 001

Object Damaged: STOCK COW	Company Owner Name:
Estimate of Damage: \$100.00	City: HARTLEY
Owner's Name - Last: BOBZIEN	State: IA
First: DONALD	Zip Code: 51246
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 06 - ANIMAL IN ROADWAY
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
Surface Conditions: 01 - DRY	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

Vehicle #1 was westbound on 360th Street near Vine Avenue. The driver just went thru a bridge and was surprised to see several stock cows and calves standing on the roadway. The driver struck one of the cows. The owner of the cattle was notified and chased the cattle back in the pasture. It is unknown which animal was struck and how badly it may have been injured.

Diagram

