

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: S18-004115	Report to All Drivers:	At Intersection with:
Date of Acc: 07/01/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 16:14 Hrs.	Private Property: YES	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	County: O'BRIEN - 71	Direction 1:
Officer: VANMEETEREN KEVEN	Acc Loc City:	Distance 2:
Badge #: 71-7	Acc Dir From City:	Direction 2:
Report Date: 07/01/2018	Closest City:	X-Coordinate: 00289764
Officer Notified: 18:09 Hrs.	Miles From City:	Y-Coordinate: 04766390
Officer Arrived: 18:26 Hrs.	Road, Street, HWay:	Location Literal: 4325 TABOR AVE
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: WALLINGA	Bus Use:	Transported to: BAUM HARMON HOSPITAL
First: DONALD		
Middle: MARRION	Drvr Distractions: 99 - UNKNOWN	Transported by: PRIVATE VEHICLE
City: PRIMGHAR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51245		
Suffix:	Point of Init 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Impact:	
Age: 12	Most Damaged 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Drvr: 58 - OPERATOR INEXPERIENCE
CDL: NO	Area:	
License State: NO	Undrrid/Ovrid: 1 - NONE	
License Class:	Rpr/Rplc Cost: \$300.00	
License Endorsmnt:	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Restrictions:	First Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 65 - BUILDING	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Third Event:	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 01	Fourth Event:	
Vehicle Year: 1984		Number of Axles:
Vehicle Make: SUZUKI - SUZI	Most Harmful 65 - BUILDING	HazMat Involvement:
Vehicle Model: LT250E	Event:	HazMat Placard:
Vehicle Style: ATV	Abg Switch Stat:	Placard #:
Vehicle Color: RED - RED	Abg Deploy: 01 - NOT APPLICABLE	HazMat Released?:
Vehicle Config: 28 - ALL-TERRAIN VEHICLE (ATV)	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Defect: 98 - OTHER (EXPLAIN IN NARRATIVE)	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Tow:	Occpnt Protect: 02 - NONE USED	Citation Charge 1:
Tow #:		Cit Chrg Code 2:
Initial Trvl Dir: 02 - EAST		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
	Source of Trans: 05 - PARENT/SPOUSE/FRIEND	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Property Damage 001

Object Damaged: BUILDING	Company Owner Name: PRODUCERS COOP
Estimate of Damage: \$500.00	City: PRIMGHAR
Owner's Name - Last:	State: IA
First:	Zip Code: 51245
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 06 - OUTSIDE TRAFFICWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
Surface Conditions: 10 - GRAVEL	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 65 - BUILDING
Type:	
Workers Present:	

Narrative

Driver of unit 1 was operating an atv on private property. The throttle stuck open on unit 1 and the driver was unable to stop the atv or shut the engine down in time before hitting a building belonging to Producer's Coop. The atv came off private property, crossed a gravel roadway and went onto property belonging to Producer's Coop. Driver was transported by private vehicle to Baum Harmon Hospital in Primghar, IA for injuries.

Diagram

