

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-004654**
 Date of Acc: **07/21/18**
 Time of Acc: **01:30** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **BRACY DANIEL**
 Badge #: **71-6**
 Report Date: **07/21/2018**
 Officer Notified: **11:28** Hrs.
 Officer Arrived: **11:30** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00286350**
 Y-Coordinate: **04772628**
 Location Literal: **US 59/SILVER AVE**
 Description:

Unit 001

Driver Name - Last: DETRICK	Bus Use:	Transported to:
First: JACQUELINE		
Middle: BELLE	Drvtr Distractions:	Transported by:
City: PRIMGAR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51245		
Suffix:	Point of Init 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Impact:	
Age: 22	Most Damaged 12 - FRONT MIDDLE	Cont. Circum., Drvr: 06 - LOST CONTROL, 98 - OTHER (EXPLAIN IN NARRATIVE)
CDL: NO	Area:	
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$5,000.00	
License Endorsmnt:	Ext of Damage: 4 - DISABLING DAMAGE	
License Restrictions: B	First Event: 03 - RAN OFF ROAD, LEFT	
Speed Limit: 55		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 44 - DITCH	Carrier Address:
Driver Condition: 03 - ASLEEP/FATIGUED		Carrier City:
Alcohol Test Given: NO	Third Event: 60 - TREE	Carrier State:
Drug Test Given: 1 - NONE		Carrier Zip:
Total Occupants: 01	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Vehicle Year: 2011		Number of Axles:
Vehicle Make: TOYOTA - TOYT	Most Harmful 60 - TREE	HazMat Involvement:
Vehicle Model: CAM	Event:	HazMat Placard:
Vehicle Style: 4D	Abg Switch Stat:	Placard #:
Vehicle Color: BLACK - BLK	Abg Deploy: 03 - NOT DEPLOYED	HazMat Released?:
Vehicle Config: 01 - PASSENGER CAR		Converter Dolly:
Vehicle Defect: 01 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	GVWR:
	Ejection: 2 - NOT EJECTED	Cit Chrg Code 1: 321.288(1)
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Tow: 3 - DISABLED - OFFICER ARRANGED	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 2:
Tow #: 18000056		Citation Charge 2:
Initial Trvl Dir: 03 - SOUTH	5 - UNINJURED	Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 44 - DITCH
Type:	
Workers Present:	

Narrative

PASSERBY CALLED IN WRECKED VEHICLE; VEHICLE WAS UNOCCUPIED WHEN I ARRIVED ON SCENE; VEHICLE APPEARED TO BE TRAVELING SOUTHBOUND WHERE IT CROSSED THE NORTHBOUND LANE OF TRAFFIC AND ENTERED THE EAST DITCH; VEHICLE TRAVELED SEVERAL HUNDRED YARDS BEFORE HITTING A TREE AND COMING TO A STOP; VEHICLE WAS TOWED TO THE COUNTY SHED

Diagram

