

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	S18-007069	Report to All Drivers:		At Intersection with:	
Date of Acc:	10/30/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	19:53 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	VANMEETEREN KEVEN	Acc Loc City:		Distance 2:	
Badge #:	71-7	Acc Dir From City:		Direction 2:	
Report Date:	10/30/2018	Closest City:		X-Coordinate:	00296509
Officer Notified:	19:53 Hrs.	Miles From City:		Y-Coordinate:	04781293
Officer Arrived:	20:15 Hrs.	Road, Street, HWay:		Location Literal:	6512 340TH ST
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	HOWARD	Bus Use:		Transported to:	
First:	TREVEN	Dvrv Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	THOMAS	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	OCHEYEDAN	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Dvrv:	88 - NO IMPROPER ACTION
Zip:	51354	Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$4,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:		Carrier City:	
Age:	32	First Event:	06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier State:	
CDL:	YES	Second Event:	31 - ANIMAL	Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	A	Fourth Event:		Number of Axles:	
License Endorsmnt:	N - TANK	Most Harmful Event:	31 - ANIMAL	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	50	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Total Occupants:	01	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Year:	2013	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	FORD - FORD			Citation Charge 2:	
Vehicle Model:	F350 SUPER DUTY			Citation Charge 3:	
Vehicle Style:				Citation Charge 4:	
Vehicle Color:	SILVER - SIL				
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Property Damage 001

Object Damaged:	1800 LB COW	Company Owner Name:	
Estimate of Damage:	\$2,500.00	City:	HARTLEY
Owner's Name - Last:	PAULSEN	State:	IA
First:	GREG	Zip Code:	51346
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	06 - ANIMAL IN ROADWAY
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	10 - GRAVEL	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	31 - ANIMAL
Type:			
Workers Present:			

Narrative

UNIT 1 EASTBOUND IN THE 6500 MILE OF 340TH ST. UNIT 1 WAS SLOWING DOWN DUE TO ANOTHER SINGLE VEHICLE ACCIDENT INVOLVING A COW. AS UNIT 1 WAS APPROACHING, AN UNKNOWN NUMBER OF COWS ENTERED THE ROADWAY AND UNIT 1 ALSO STRUCK A COW.

Diagram



340TH ST

