

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-007438	Report to All Drivers:	At Intersection with:
Date of Acc: 11/17/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 06:50 Hrs.	Private Property: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	County: O'BRIEN - 71	Direction 1:
Officer: DEPUTY STEVEN VANDERVEEN	Acc Loc City:	Distance 2:
Badge #: 71-9	Acc Dir From City:	Direction 2:
Report Date: 11/17/2018	Closest City:	X-Coordinate: 00281813
Officer Notified: 09:46 Hrs.	Miles From City:	Y-Coordinate: 04773689
Officer Arrived: 09:46 Hrs.	Road, Street, HWay:	Location Literal: B040/390TH ST
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: RODRIGUEZ CANCINO	Bus Use:	Transported to:
First: HERSAIN		
Middle:	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: PRIMGHAR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51245-0000		
Suffix:	Point of Init: 99 - UNKNOWN	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Impact:	
Age: 22	Most Damaged Area: 04 - REAR PASSENGER SIDE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
CDL: NO	Undridd/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$3,000.00	
License Class: C	Ext of Damage: 4 - DISABLING DAMAGE	
License Endorsmnt:	First Event: 11 - LOSS OF TRACTION	
License Restrictions: B		Carrier Name:
Speed Limit: 55	Second Event: 03 - RAN OFF ROAD, LEFT	Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER		Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event: 20 - OVERTURN/ROLLOVER	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1		
Vehicle Year: 1998	Most Harmful Event: 20 - OVERTURN/ROLLOVER	Number of Axles:
Vehicle Make: FORD - FORD	Abg Switch Stat:	HazMat Involvement:
Vehicle Model: EXPEDITION	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Vehicle Style: SUV		Placard #:
Vehicle Color: BLUE - BLU	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Ejection: 2 - NOT EJECTED	Converter Dolly:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:
Tow: 6 - ABANDONED/LEFT AT SCENE		Citation Charge 1:
Tow #: 02 - EAST		Cit Chrg Code 2:
Initial Trvl Dir: 02 - EAST		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 3 - DAWN	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
Surface Conditions: 03 - ICE/FROST	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Workzone Related: NO	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: 20 - OVERTURN/ROLLOVER
Workers Present:	

Narrative

VEHICLE #1 WAS EASTBOUND ON 390TH STREET. THE ROAD WAS VERY SLIPPERY WITH BLACK ICE. THE DRIVER LOST TRACTION WENT INTO THE NORTH DITCH AND ROLLED OVER.

Diagram

