

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	18-008149	Report to All Drivers:		At Intersection with:	
Date of Acc:	12/19/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	08:30 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	ROHRBAUGH TIMOTHY	Acc Loc City:		Distance 2:	
Badge #:	71-5	Acc Dir From City:		Direction 2:	
Report Date:	12/19/2018	Closest City:		X-Coordinate:	00297240
Officer Notified:	08:30 Hrs.	Miles From City:		Y-Coordinate:	04763233
Officer Arrived:	08:45 Hrs.	Road, Street, HWay:		Location Literal:	M012/VINE AVE
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	BROWN	Bus Use:		Transported to:	
First:	JEROME	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	DURON	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	CHEROKEE	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	13 - TOP OF VEHICLE	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51012-0000	Undridd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$5,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	59	First Event:	11 - LOSS OF TRACTION	Carrier State:	
CDL:	NO	Second Event:	44 - DITCH	Carrier Zip:	
License State:	IA	Third Event:	20 - OVERTURN/ROLLOVER	Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	20 - OVERTURN/ROLLOVER	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	2 - EXTRICATED BY NON-MECHIA	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Total Occupants:	2	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Year:	2002	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	JEEP - JEEP			Citation Charge 2:	
Vehicle Model:	GRAND CHEROKEE			Citation Charge 3:	
Vehicle Style:	SUV			Citation Charge 4:	
Vehicle Color:	BLACK - BLK				
Vehicle Config:	03 - SPORT UTILITY VEHICLE				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	18-00099				
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Property Damage 001

Object Damaged:	FENCE	Company Owner Name:	
Estimate of Damage:	\$500.00	City:	SUTHERLAND
Owner's Name - Last:	LENHART	State:	IA
First:	LUKE	Zip Code:	51058
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	98 - OTHER (EXPLAIN IN NARRATIVE)
Light Conditions:	1 - DAYLIGHT	Roadway:	01 - NONE APPARENT
Weather Conditions:	02 - CLOUDY, 03 - FOG, SMOKE, SMOG	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	03 - ICE/FROST	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

THE VEHICLE WAS TRAVELING SOUTH ON VINE AVE. WHEN IT CAME UPON BLACK ICE AND LOST CONTROL. THE VEHICLE ENTERED THE EAST DITCH AND WENT AIRBORNE AND CAME TO REST ON ITS ROOF. THE VEHICLE WENT THROUGH A FARMERS FENCE IN TWO LOCATIONS

Diagram

