

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	19-000271	Report to All Drivers:		At Intersection with:	
Date of Acc:	01/11/19	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	23:00 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	VANDERVEEN STEVEN	Acc Loc City:		Distance 2:	
Badge #:	71-9	Acc Dir From City:		Direction 2:	
Report Date:	01/11/2019	Closest City:		X-Coordinate:	00270616
Officer Notified:	23:08 Hrs.	Miles From City:		Y-Coordinate:	04783720
Officer Arrived:	23:14 Hrs.	Road, Street, HWay:		Location Literal:	NEST AVE AND B020/330TH ST
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	VAN GORP	Bus Use:		Transported to:	SHELDON HOSPITAL
First:	ERICA	Drvr Distractions:	97 - OTHER DISTRACTION INSIDE VEHICLE (EXPLAIN IN NARRATIVE)	Transported by:	SHELDON AMBULANCE
Middle:	BETH	Traffic Controls:	04 - STOP SIGNS	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SHELDON	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	02 - RAN STOP SIGN
Zip:	51201-0000	Undrrid/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$10,000.00	Carrier Address:	
Gender:	Female	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	38	First Event:	94 - OTHER PRE-CRASH (EXPLAIN IN NARRATIVE)	Carrier State:	
CDL:	NO	Second Event:	33 - VEHICLE IN TRAFFIC	Carrier Zip:	
License State:	IA	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Class:	B	Fourth Event:		Number of Axles:	
License Endorsmnt:	NPS	Most Harmful Event:	33 - VEHICLE IN TRAFFIC	HazMat Involvement:	
License Restrictions:	3M	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	35	Abg Deploy:	04 - DEPLOYED FRONT OF PERSON	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	98 - OTHER (EXPLAIN IN NARRATIVE)	Cit Chrg Code 1:	321.322(1)
Total Occupants:	1	Source of Trans:	03 - EMS GROUND	Citation Charge 1:	FAIL TO OBEY STOP SIGN AND YIELD RIGHT OF WAY
Vehicle Year:	2008	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 2:	
Vehicle Make:	CHRYSLER - CHRY			Citation Charge 3:	
Vehicle Model:	TOW			Citation Charge 4:	
Vehicle Style:	VN				
Vehicle Color:	SILVER - SIL				
Vehicle Config:	04 - PASSENGER VAN (SEATS <9)				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	3 - DISABLED - OFFICER ARRANGED				
Tow #:	19-0006				
Initial Trvl Dir:	03 - SOUTH				
Vision Obscured:	01 - NOT OBSCURED				

Unit 002

Driver Name - Last: SCHWARZ	Bus Use:	Transported to: SHELDON HOSPITAL
First: DENNIS		
Middle: EDWARD	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: SHELDON HOSPITAL
City: ASHTON		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51232-0000		
Suffix:	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 48	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,000.00	
License State: IA	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Class: C	First Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier Name:
License Endorsmnt: L	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier Address:
License Restrictions:	Third Event: 97 - OTHER FIXED OBJECT (EXPLAIN IN NARRATIVE)	Carrier City:
Speed Limit: 55	Fourth Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Abg Switch Stat:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Abg Deploy: 03 - NOT DEPLOYED	Number of Axles:
Drug Test Given: 1 - NONE	Trapped: 3 - EXTRICATED BY MECHANICAL	HazMat Involvement:
Total Occupants: 3	Ejection: 2 - NOT EJECTED	HazMat Placard:
Vehicle Year: 1997	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Placard #:
Vehicle Make: PONTIAC - PONT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	HazMat Released?:
Vehicle Model: BON	Source of Trans: 03 - EMS GROUND	Converter Dolly:
Vehicle Style: 4D	Died at Scene: 01 - NOT APPLICABLE	GVWR:
Vehicle Color: WHITE - WHI		Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 2:
Tow: 3 - DISABLED - OFFICER ARRANGED		Cit Chrg Code 3:
Tow #: 19-0005		Citation Charge 3:
Initial Trvl Dir: 02 - EAST		Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED		

Property Damage 001

Object Damaged: PHONE PAD	Company Owner Name: NORTHWESTERN BELL -- UNKNOWN
Estimate of Damage: \$500.00	City:
Owner's Name - Last:	State:
First:	Zip Code:
Middle:	
Suffix:	

Property Damage 002

Object Damaged: FIBER OPTIC PAD	Company Owner Name: PRIMIER COMMUNICATIONS
Estimate of Damage: \$1,000.00	City: SIOUX CENTER
Owner's Name - Last:	State: IA
First:	Zip Code: 51250
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 05 - BROADSIDE (FRONT TO SIDE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	FRA No.:
	Horizontal Alignment:
Workzone Related: NO	Vertical Alignment:
Activity:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Location:	
Type:	
Workers Present:	

Injured Person 001

Name - Last: FISHER
First: BRICE
Middle:
Suffix:
City:
State:
Zip Code:
Age: 21
Sex: MALE
Unit No.: 2
Seating Position: 06 - 2ND ROW: RIGHT SIDE
Occupant Protection: 02 - NONE USED

Airbag Deployment: 01 - NOT APPLICABLE
Airbag Switch Status:
Trapped: 1 - NOT TRAPPED/APPLICABLE
Injury Status: 2 - SUSPECTED SERIOUS/INCAPACITATING
Ejection: 4 - TOTALLY EJECTED
Ejection Path: 06 - THROUGH BACK WINDOW
Alcohol Test Given:
Drug Test Given:
Source of Transport: 03 - EMS GROUND
Died at Scene/Enroute: 01 - NOT APPLICABLE
Transported to: SHELDON HOSPITAL
Transported by: SHELDON AMBULANCE

Injured Person 002

Name - Last: SCHWARZ
First: LISA
Middle: JEANE
Suffix:
City: ASHTON
State: IA
Zip Code: 51232
Age: 40
Sex: FEMALE
Unit No.: 2
Seating Position: 03 - 1ST ROW: RIGHT SIDE
Occupant Protection: 03 - SHOULDER AND LAP BELT USED

Airbag Deployment: 03 - NOT DEPLOYED
Airbag Switch Status:
Trapped: 1 - NOT TRAPPED/APPLICABLE
Injury Status: 4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)
Ejection: 2 - NOT EJECTED
Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE
Alcohol Test Given:
Drug Test Given:
Source of Transport: 03 - EMS GROUND
Died at Scene/Enroute: 01 - NOT APPLICABLE
Transported to: SHELDON HOSPITAL
Transported by: SHELDON AMBULANCE

Narrative

VEHICLE #1 WAS SOUTHBOUND ON COUNTRY CLUB ROAD. THE DRIVER HAD JUST STARTED DRIVING A SHORT TIME BEFORE AND REALIZED SHE HAD NOT PUT ON HER SEAT BELT. THE DRIVER REACHED OVER TO PUT ON HER BELT. VEHICLE #2 WAS EASTBOUND ON 330TH STREET. THE DRIVER OF VEHICLE #1 WAS FOCUSED ON HER SEAT BELT AND DIDN'T REALIZE SHE WAS ALREADY AT THE INTERSECTION. THE DRIVER OF VEHICLE #1 DID NOT STOP FOR THE STOP SIGN AND STRUCK VEHICLE #2 IN THE DRIVERS DOOR. BOTH VEHICLES ENTERED THE DITCH SOUTH EAST OF THE INTERSECTION. VEHICLE #2 ALSO STRUCK TWO FIBER OPTIC PADS WHILE IN THE DITCH. A REAR SEAT PASSENGER OF VEHICLE #2 WAS NOT WEARING A SEAT BELT AND WAS EJECTED FROM THE VEHICLE.

Diagram

