

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 19-001411
 Date of Acc: 03/05/19
 Time of Acc: 20:42 Hrs.
 Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF
 Officer: VANDERVEEN STEVEN
 Badge #: 71-9
 Report Date: 03/05/2019
 Officer Notified: 20:47 Hrs.
 Officer Arrived: 21:01 Hrs.
 Scene Investigated: YES

Report to All Drivers:
 Legal Intervention: NO
 Private Property: NO
 County: O'BRIEN - 71
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: 00278127
 Y-Coordinate: 04762439
 Location Literal: STATE 10/460TH ST
 Description:

Unit 001

Driver Name - Last: FULLERTON	Bus Use:	Transported to:
First: CASSANDRA		
Middle: MARIE	Drvtr Distractions: 99 - UNKNOWN	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51045-0000		
Suffix:	Point of Init 99 - UNKNOWN	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Impact:	
Age: 24	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
CDL: NO	Undrdr/Ovrid: 1 - NONE	
License State: IA	Rpr/Rplc Cost: \$5,000.00	
License Class: C	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Endorsmnt:	First Event: 11 - LOSS OF TRACTION	
License Restrictions: B		Carrier Name:
Speed Limit: 55		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 42 - BRIDGE/BRIDGE RAIL PARAPET	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Third Event:	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1	Fourth Event:	
Vehicle Year: 2003		Number of Axles:
Vehicle Make: CHRYSLER - CHRY		HazMat Involvement:
Vehicle Model: CNC	Most Harmful Event: 42 - BRIDGE/BRIDGE RAIL PARAPET	HazMat Placard:
Vehicle Style: 4D		Placard #:
Vehicle Color: BLUE - BLU	Abg Switch Stat:	HazMat Released?:
Vehicle Config: 01 - PASSENGER CAR	Abg Deploy: 04 - DEPLOYED FRONT OF PERSON	Converter Dolly:
Vehicle Defect: 99 - UNKNOWN		GVWR:
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Cit Chrg Code 1: 321.288(1)
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection: 2 - NOT EJECTED	Citation Charge 1: FAILURE TO MAINTAIN CONTROL
Tow: 3 - DISABLED - OFFICER ARRANGED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	
Tow #: 19-0038	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 2:
Initial Trvl Dir: 02 - EAST		Citation Charge 2:
Vision Obscured: 01 - NOT OBSCURED	4 - POSSIBLE (COMPLAINT OF PAIN/INJURY)	Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 96 - OTHER NON-INTERSECTION (EXPLAIN IN NARRATIVE)
Surface Conditions: 03 - ICE/FROST	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 42 - BRIDGE/BRIDGE RAIL PARAPET
Workers Present:	

Narrative

Vehicle #1 was driven by Cassandra Fullerton and was heading east on Highway 10 approximately two miles west of Paullina. The driver was catching up to a car and applied the brakes. The driver lost control and slid into a guard rail on a bridge. The car came to rest in the middle of the bridge in the dark.

