

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **19-001415**
 Date of Acc: **03/05/19**
 Time of Acc: **20:50** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **VANDERVEEN STEVEN**
 Badge #: **71-9**
 Report Date: **03/05/2019**
 Officer Notified: **21:01** Hrs.
 Officer Arrived: **21:01** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00278127**
 Y-Coordinate: **04762439**
 Location Literal: **STATE 10/460TH ST**
 Description:

Unit 001

Driver Name - Last: **SHRIVER**
 First: **RYAN**
 Middle: **MICHAEL**
 City: **GRANVILLE**
 State: **IA**
 Zip: **51022-0000**
 Suffix:
 Gender: **Male**
 Age: **32**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2005**
 Vehicle Make: **DODGE - DODG**
 Vehicle Model: **CVN**
 Vehicle Style: **VN**
 Vehicle Color: **BLUE - BLU**
 Vehicle Config: **04 - PASSENGER VAN (SEATS <9)**
 Vehicle Defect: **99 - UNKNOWN**
 Vehicle Action: **01 - MOVEMENT ESSENTIALLY STRAIGHT**
 Tow: **3 - DISABLED - OFFICER ARRANGED**
 Tow #: **19-0039**
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **98 - DISTRACTION OUTSIDE VEHICLE (EXPLAIN IN NARRATIVE)**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **12 - FRONT MIDDLE**
 Most Damaged Area: **12 - FRONT MIDDLE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$5,000.00**
 Ext of Damage: **5 - SEVERE, VEHICLE TOTALED**
 First Event: **35 - PARKED MOTOR VEHICLE**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **35 - PARKED MOTOR VEHICLE**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **99 - UNKNOWN**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 99 - UNKNOWN	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
CDL:	Undrrid/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$5,000.00	
License Class:	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Endorsmnt:	First Event:	Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit:		Carrier City:
Seating Position:	Second Event:	Carrier State:
		Carrier Zip:
Driver Condition:	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given:		
Drug Test Given:	Fourth Event:	Number of Axles:
Total Occupants: 0		HazMat Involvement:
Vehicle Year: 2003		HazMat Placard:
Vehicle Make: CHRYSLER - CHRY	Most Harmful Event:	Placard #:
Vehicle Model: CNC		HazMat Released?:
Vehicle Style: 4D	Abg Switch Stat:	Converter Dolly:
Vehicle Color: BLUE - BLU	Abg Deploy:	GVWR:
Vehicle Config: 01 - PASSENGER CAR		Cit Chrg Code 1:
	Trapped:	Citation Charge 1:
Vehicle Defect: 05 - OTHER TIRE DEFECT (EXPLAIN IN NARRATIVE)	Ejection:	
Vehicle Action: 13 - ILLEGALLY PARKED/UNATTENDED	Ejection Path:	Cit Chrg Code 2:
Tow: 3 - DISABLED - OFFICER ARRANGED	Occpnt Protect:	Citation Charge 2:
Tow #: 19-0038		
Initial Trvl Dir:	Source of Trans:	Citation Charge 3:
Vision Obscured:	Died at Scene:	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 98 - OTHER (EXPLAIN IN NARRATIVE)	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 96 - OTHER NON-INTERSECTION (EXPLAIN IN NARRATIVE)
Surface Conditions: 03 - ICE/FROST	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Workers Present:	

Narrative

Vehicle #1 was driven by Ryan Shriver and was heading east on Highway 10 approximately 2 miles west of Paullina. There had been two previous accidents in this bridge within the last several minutes. The driver of Vehicle #1 saw the Paulsen vehicle parked on the west edge of the bridge with its flashers on. The driver of Vehicle #1 was distracted by this car parked on the side of the road. At the last moment the driver of #1 saw Cassandra Fullerton standing in the roadway waving her cell phone trying to get his attention. The driver of Vehicle #1 did not see Vehicle #2 which was parked in the middle of the bridge after two separate collisions. The driver of Vehicle #1 was unable to stop in time due to icy road conditions. Vehicle #1 then collided with Vehicle #2 which was unoccupied.

Diagram

