

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	19-001621	Report to All Drivers:	At Intersection with:
Date of Acc:	03/14/19	Legal Intervention:	Div HWay Trvl Dir:
Time of Acc:	15:15 Hrs.	Private Property:	Distance 1:
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	Direction 1:
Officer:	VANDERVEEN STEVEN	Acc Loc City:	Distance 2:
Badge #:	71-9	Acc Dir From City:	Direction 2:
Report Date:	03/14/2019	Closest City:	X-Coordinate:
Officer Notified:	15:27 Hrs.	Miles From City:	Y-Coordinate:
Officer Arrived:	15:45 Hrs.	Road, Street, HWay:	Location Literal:
Scene Investigated:	YES	Definable Location:	Description:
		Milepost Number:	

Unit 001

Driver Name - Last:	HANSEN	Bus Use:	Transported to:
First:	MICHELLE	Drvr Distractions:	Transported by:
Middle:	ANN	Traffic Controls:	Special Veh Func:
City:	PRIMGHAR	Point of Init Impact:	Emergency Status:
State:	IA	Most Damaged Area:	Cont. Circum., Drvr:
Zip:	51245	Undrrid/Ovrid:	Carrier Name:
Suffix:		Rpr/Rplc Cost:	Carrier Address:
Gender:	Female	Ext of Damage:	Carrier City:
Age:	31	First Event:	Carrier State:
CDL:	NO	Second Event:	Carrier Zip:
License State:	IA	Third Event:	Cargo Body Type:
License Class:	0	Fourth Event:	Number of Axles:
License Endorsmnt:		Most Harmful Event:	HazMat Involvement:
License Restrictions:	SR-22	Abg Switch Stat:	HazMat Placard:
Speed Limit:	55	Abg Deploy:	Placard #:
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	HazMat Released?:
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	Converter Dolly:
Alcohol Test Given:	NO	Ejection Path:	GVWR:
Drug Test Given:	1 - NONE	Occpnt Protect:	Cit Chrg Code 1:
Total Occupants:	1	Source of Trans:	Citation Charge 1:
Vehicle Year:	2006	Died at Scene:	Citation Charge 2:
Vehicle Make:	CHEVROLET - CHEV		Citation Charge 3:
Vehicle Model:	SLV		Citation Charge 4:
Vehicle Style:	PK		
Vehicle Color:	WHITE - WHI		
Vehicle Config:	02 - FOUR-TIRE TRUCK (PICK-UP)		
Vehicle Defect:	99 - UNKNOWN		
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow:	6 - ABANDONED/LEFT AT SCENE		
Tow #:			
Initial Trvl Dir:	02 - EAST		
Vision Obscured:	01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:
Light Conditions:	1 - DAYLIGHT	Roadway:
Weather Conditions:	07 - SNOW	Type of Road Junc/Feat:
Surface Conditions:	05 - SLUSH	FRA No.:
Workzone Related:	NO	Horizontal Alignment:
Activity:		Vertical Alignment:
Location:		First Harmful Evt of Crash:
Type:		
Workers Present:		

Narrative

Vehicle #1 was eastbound on 390th Street. The driver was going up the hill near 5439 390th Street. The driver lost control due to some slush on the road. The driver entered the south ditch and rolled over coming to rest on its roof.

Diagram

