

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	19-003335	Report to All Drivers:		At Intersection with:	
Date of Acc:	05/23/19	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	05:00 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	VANDERVEEN STEVEN	Acc Loc City:		Distance 2:	
Badge #:	71-9	Acc Dir From City:		Direction 2:	
Report Date:	05/23/2019	Closest City:		X-Coordinate:	00270231
Officer Notified:	05:27 Hrs.	Miles From City:		Y-Coordinate:	04772419
Officer Arrived:	05:43 Hrs.	Road, Street, HWay:		Location Literal:	B040/400TH ST
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	VANDE VEGTE	Bus Use:		Transported to:	ORANGE CITY HOSPITAL
First:	CHRISTINA	Dvr Distractions:	02 - NOT DISTRACTED	Transported by:	HOSPERS AMBULANCE
Middle:	MARIE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SPENCER	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Dvr:	06 - LOST CONTROL
Zip:	51301-0000	Undridd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$4,000.00	Carrier Address:	
Gender:	Female	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	35	First Event:	03 - RAN OFF ROAD, LEFT	Carrier State:	
CDL:	NO	Second Event:	47 - CULVERT/PIPE OPENING	Carrier Zip:	
License State:	IA	Third Event:	23 - VEHICLE WENT AIRBORNE	Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:	44 - DITCH	Number of Axles:	
License Endorsmnt:		Most Harmful Event:	44 - DITCH	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	04 - DEPLOYED FRONT OF PERSON	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	03 - ASLEEP/FATIGUED	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	321.288(1)
Total Occupants:	1	Source of Trans:	03 - EMS GROUND	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Year:	2001	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	MAZDA - MAZD			Citation Charge 2:	
Vehicle Model:	626 ES/LX			Citation Charge 3:	
Vehicle Style:	4D			Citation Charge 4:	
Vehicle Color:	BLUE - BLU				
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	02 - SHOULDER	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	47 - CULVERT/PIPE OPENING
Type:			
Workers Present:			

Narrative

Driver #1 was westbound on 400th Street. The driver apparently fell asleep and veered gradually off the road into the left ditch. The car impacted a field drive and vaulted. The car came down on its front bumper and came to rest in an un-planted field.

