

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	17-004622	Report to All Drivers:	YES	At Intersection with:	"N/A"
Date of Acc:	07/12/17	Legal Intervention:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	12:05 Hrs.	Private Property:	NO	Distance 1:	"N/A"
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	"N/A"
Officer:	BRACY DANIEL	Acc Loc City:	PRIMGHAR - 6240	Distance 2:	"N/A"
Badge #:	71-6	Acc Dir From City:	"N/A"	Direction 2:	"N/A"
Report Date:	07/12/2017	Closest City:	"N/A"	X-Coordinate:	00286178
Officer Notified:	12:09 Hrs.	Miles From City:	"N/A"	Y-Coordinate:	04773753
Officer Arrived:	12:10 Hrs.	Road, Street, HWay:	"N/A"	Location Literal Description:	1ST ST SE AND S HAYES AVE AND 1ST ST SW
Scene Investigated:	NO	Definable Location:	"N/A"		
		Milepost Number:	"N/A"		

Unit 001

Driver Name - Last:	FRITZSCHE	Bus Use:		Transported to:	
First:	JESSIE	Drv Distractions:	01 - NOT APPLICABLE/NO DRIVER	Transported by:	
Middle:	GRACE	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	PRIMGHAR	Point of Init Impact:	07 - REAR DRIVER SIDE CORNER	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr:	99 - UNKNOWN
Zip:	51245-0000	Undrrid/Ovrid:	1 - NONE		
Suffix:		Rpr/Rplc Cost:	\$250.00	Carrier Name:	
Gender:	Female	Ext of Damage:	2 - MINOR DAMAGE	Carrier Address:	
Age:	85	First Event:	98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier City:	
CDL:	NO	Second Event:		Carrier State:	
License State:	IA	Third Event:		Carrier Zip:	
License Class:	C	Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Most Harmful Event:	98 - OTHER (EXPLAIN IN NARRATIVE)	Number of Axles:	
License Restrictions:	NONE	Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	0	Abg Deploy:	01 - NOT APPLICABLE	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	99 - UNKNOWN	Ejection:	1 - NOT APPLICABLE	HazMat Released?:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	01 - NOT APPLICABLE	GVWR:	
Total Occupants:	0	Injury Status:	5 - UNINJURED	Cit Chrg Code 1:	
Vehicle Year:	2000	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Make:	BUICK - BUIC	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Model:	CEN			Citation Charge 2:	
Vehicle Style:	4D			Cit Chrg Code 3:	
Vehicle Color:	BEIGE - BGE			Citation Charge 3:	
Vehicle Config:	01 - PASSENGER CAR			Cit Chrg Code 4:	
Vehicle Defect:	01 - NONE			Citation Charge 4:	
Vehicle Action:	98 - OTHER (EXPLAIN IN NARRATIVE)				
Tow:					
Tow #:					
Initial Trvl Dir:	99 - UNKNOWN				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	98 - OTHER (EXPLAIN IN NARRATIVE)	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	1 - DAYLIGHT	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	01 - DRY	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	72 - HIT AND RUN
Type:			
Workers Present:			

Narrative

VEHICLE WAS PARKED IN VETERAN MEMORIAL PARKING LOT ON THE SW CORNER OF 1ST ST SE AND SOUTH HAYES AVE; DRIVER PARKED THE CAR AND WENT INSIDE COMMUNITY BUILDING FOR LUNCH; WHEN DRIVER CAME OUT AFTER LUNCH SHE SAW THE REAR DRIVER'S SIDE TAIL LIGHT HAD BEEN BROKEN; NOBODY WITNESSED THE ACCIDENT; SOMETHING APPEARS TO HAVE PUNCTURED AND BROKEN THE TAIL LIGHT

