

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

| | | |
|---|--------------------------------------|---|
| Case Number: 18-003133 | Report to All Drivers: Yes | At Intersection with: |
| Date of Acc: 05/25/18 | Legal Intervention: No | Div HWay Trvl Dir: |
| Time of Acc: 15:05 Hrs. | Private Property: Yes | Distance 1: |
| Name of Agency: O'Brien County Sheriff's Off | County: O'Brien - 71 | Direction 1: |
| Officer: BRACY DANIEL | Acc Loc City: Pringhar - 6240 | Distance 2: |
| Badge #: 71-6 | Acc Dir From City: | Direction 2: |
| Report Date: 05/25/2018 | Closest City: | X-Coordinate: 00286415 |
| Officer Notified: 15:06 Hrs. | Miles From City: | Y-Coordinate: 04774411 |
| Officer Arrived: 15:06 Hrs. | Road, Street, HWay: | Location Literal: US 59/RERICK AVE |
| Scene Investigated: Yes | Definable Location: | Description: |
| | Milepost Number: | |

Unit 001

| | | |
|--|--|---|
| Driver Name - Last: MAHLER | Bus Use: | Transported to: |
| First: JESSICA | | |
| Middle: NICOLE | Drvr Distractions: 16 - Looked but did not see | Transported by: |
| City: SUTHERLAND | | |
| State: IA | Traffic Controls: 01 - No controls present | Special Veh Func: 01 - No special function |
| Zip: 51058-0000 | | |
| Suffix: | Point of Init Impact: 06 - Rear Middle | Emergency Status: 01 - Not applicable |
| Gender: Female | Most Damaged Area: 06 - Rear Middle | Cont. Circum., Drvr: 98 - Other (explain in narrative) |
| Age: 38 | Undrrid/Ovrid: 1 - None | |
| CDL: No | Rpr/Rplc Cost: \$50.00 | |
| License State: IA | Ext of Damage: 1 - None | |
| License Class: C | First Event: 33 - Vehicle in traffic | Carrier Name: |
| License Endorsmnt: | | Carrier Address: |
| License Restrictions: | Second Event: 38 - Struck/struck by object/cargo/person from other vehi | Carrier City: |
| Speed Limit: | | Carrier State: |
| Seating Position: 01 - 1st row: left side/motorcycle driver | Third Event: | Carrier Zip: |
| Driver Condition: 01 - Apparently normal | | Cargo Body Type: 01 - Not applicable |
| Alcohol Test Given: NO | Fourth Event: | Number of Axles: |
| Drug Test Given: 1 - None | | HazMat Involvement: |
| Total Occupants: 01 | Most Harmful Event: 38 - Struck/struck by object/cargo/person from other vehi | HazMat Placard: |
| Vehicle Year: 2005 | | Placard #: |
| Vehicle Make: Ford - FORD | Abg Switch Stat: | HazMat Released?: |
| Vehicle Model: F15 | Abg Deploy: 01 - Not applicable | Converter Dolly: |
| Vehicle Style: PK | | GVWR: |
| Vehicle Color: TAN - TAN | Trapped: 1 - Not trapped/applicable | Cit Chrg Code 1: |
| Vehicle Config: 02 - Four-tire truck (pick-up) | Ejection: 2 - Not ejected | Citation Charge 1: |
| Vehicle Defect: 01 - None | Ejection Path: 01 - Not ejected/not applicable | Cit Chrg Code 2: |
| Vehicle Action: 09 - Backing | | Citation Charge 2: |
| Tow: 1 - Driven away | Occpnt Protect: 03 - Shoulder and lap belt used | Cit Chrg Code 3: |
| Tow #: | | Citation Charge 3: |
| Initial Trvl Dir: 01 - North | Injury Status: 5 - Uninjured | Cit Chrg Code 4: |
| Vision Obscured: 01 - Not obscured | | Citation Charge 4: |
| | Source of Trans: 01 - Not Transported | |
| | Died at Scene: 01 - Not applicable | |

Unit 002

| | | |
|--|--|---|
| Driver Name - Last: WOHLFARTH | Bus Use: | Transported to: |
| First: JOHNNIE | | |
| Middle: JEWEL | Drvr Distractions: 16 - Looked but did not see | Transported by: |
| City: HARTLEY | | |
| State: IA | Traffic Controls: 01 - No controls present | Special Veh Func: 01 - No special function |
| Zip: 51346-0000 | | |
| Suffix: | Point of Init Impact: 07 - Rear Driver Side Corner | Emergency Status: 01 - Not applicable |
| Gender: Female | Most Damaged Area: 07 - Rear Driver Side Corner | Cont. Circum., Drvr: 98 - Other (explain in narrative) |
| Age: 59 | Undrdr/Ovrid: 1 - None | |
| CDL: No | Rpr/Rplc Cost: \$800.00 | Carrier Name: |
| License State: IA | Ext of Damage: 2 - Minor damage | Carrier Address: |
| License Class: C | First Event: 33 - Vehicle in traffic | Carrier City: |
| License Endorsmnt: B | | Carrier State: |
| License Restrictions: B | Second Event: 38 - Struck/struck by object/cargo/person from other vehi | Carrier Zip: |
| Speed Limit: | Third Event: | Cargo Body Type: 01 - Not applicable |
| Seating Position: 01 - 1st row: left side/motorcycle driver | Fourth Event: | Number of Axles: |
| Driver Condition: 01 - Apparently normal | Most Harmful Event: 38 - Struck/struck by object/cargo/person from other vehi | HazMat Involvement: |
| Alcohol Test Given: NO | Abg Switch Stat: | HazMat Placard: |
| Drug Test Given: 1 - None | Abg Deploy: 01 - Not applicable | Placard #: |
| Total Occupants: 01 | Trapped: 1 - Not trapped/applicable | HazMat Released?: |
| Vehicle Year: 2011 | Ejection: 2 - Not ejected | Converter Dolly: |
| Vehicle Make: Kia - KIA | Ejection Path: 01 - Not ejected/not applicable | GVWR: |
| Vehicle Model: OPT | Occpnt Protect: 03 - Shoulder and lap belt used | Cit Chrg Code 1: |
| Vehicle Style: 4D | Injury Status: 5 - Uninjured | Citation Charge 1: |
| Vehicle Color: GRAY - GRY | Source of Trans: 01 - Not Transported | Cit Chrg Code 2: |
| Vehicle Config: 01 - Passenger car | Died at Scene: 01 - Not applicable | Citation Charge 2: |
| Vehicle Defect: 01 - None | | Cit Chrg Code 3: |
| Vehicle Action: 09 - Backing | | Citation Charge 3: |
| Tow: 1 - Driven away | | Cit Chrg Code 4: |
| Tow #: | | Citation Charge 4: |
| Initial Trvl Dir: 03 - South | | |
| Vision Obscured: 01 - Not obscured | | |

Accident Environment

| | |
|---|---|
| First Harmful Event Loc: 98 - Other (explain in narrative) | Roadway Characteristics |
| Manner of Crash/Collision: 08 - Rear to rear | Environment: 01 - None apparent |
| Light Conditions: 1 - Daylight | Roadway: 01 - None apparent |
| Weather Conditions: 01 - Clear | |
| Surface Conditions: 01 - Dry | Type of Road Junc/Feat: 96 - Other non-intersection (explain in narrative) |
| Workzone Related: No | FRA No.: |
| Activity: | Horizontal Alignment: |
| Location: | Vertical Alignment: |
| Type: | First Harmful Evt of Crash: 33 - Vehicle in traffic |
| Workers Present: | |

Narrative

DRIVER OF VEHICLE 001 BACKED EAST AND THEN NORTH OUT OF PARKING STALL; DRIVER OF VEHICLE 001 LOOKED BUT DID NOT SEE VEHICLE 002; DRIVER OF VEHICLE 002 BACKED SOUTH OUT OF PARKING STALL; DRIVER OF VEHICLE 002 LOOKED BUT DID NOT SEE VEHICLE 001; VEHICLE 001 AND VEHICLE 002 COLLIDED; VEHICLE 001'S TRAILER HITCH COLLIDED WITH VEHICLE 002 LEFT REAR BUMPER

