

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	18-007467	Report to All Drivers:		At Intersection with:	
Date of Acc:	11/18/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	12:40 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY STEVEN VANDERVEEN	Acc Loc City:		Distance 2:	
Badge #:	71-9	Acc Dir From City:		Direction 2:	
Report Date:	11/18/2018	Closest City:		X-Coordinate:	00296093
Officer Notified:	12:52 Hrs.	Miles From City:		Y-Coordinate:	04773253
Officer Arrived:	13:02 Hrs.	Road, Street, HWay:		Location Literal:	B040/390TH ST
Scene Investigated:	YES	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	STOUT	Bus Use:		Transported to:	
First:	ESTELLA	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	PEARL	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	PRIMGHAR	Point of Init Impact:	99 - UNKNOWN	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	13 - TOP OF VEHICLE	Cont. Circum., Drvr:	06 - LOST CONTROL
Zip:	51245-0000	Undridd/Ovrid:	1 - NONE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$3,500.00	Carrier Address:	
Gender:	Female	Ext of Damage:	5 - SEVERE, VEHICLE TOTALED	Carrier City:	
Age:	82	First Event:	11 - LOSS OF TRACTION	Carrier State:	
CDL:	NO	Second Event:	03 - RAN OFF ROAD, LEFT	Carrier Zip:	
License State:	IA	Third Event:	20 - OVERTURN/ROLLOVER	Cargo Body Type:	01 - NOT APPLICABLE
License Class:	C	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	20 - OVERTURN/ROLLOVER	HazMat Involvement:	
License Restrictions:	B	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	Placard #:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Released?:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Converter Dolly:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	GVWR:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	Citation Charge 1:	
Vehicle Year:	2001	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 2:	
Vehicle Make:	CHEVROLET - CHEV			Citation Charge 2:	
Vehicle Model:	BLAZER			Citation Charge 3:	
Vehicle Style:	SUV			Citation Charge 4:	
Vehicle Color:	WHITE - WHI				
Vehicle Config:	03 - SPORT UTILITY VEHICLE				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Property Damage 001

Object Damaged:	STOP SIGN	Company Owner Name:	O'BRIEN COUNTY
Estimate of Damage:	\$200.00	City:	PRIMGHAR
Owner's Name - Last:		State:	IA
First:		Zip Code:	51245
Middle:			
Suffix:			

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	1 - DAYLIGHT	Roadway:	01 - NONE APPARENT
Weather Conditions:	01 - CLEAR	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	03 - ICE/FROST	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	20 - OVERTURN/ROLLOVER
Type:			
Workers Present:			

Narrative

VEHICLE #1 WAS WESTBOUND ON 390TH STREET. THE DRIVER LOST CONTROL ON PATCHY ICE THAT WAS JUST BEGINNING TO MELT. THE DRIVER WENT IN THE SOUTH DITCH AND ROLLED COMING TO REST ON ITS ROOF. THE CAR KNOCKED OVER A STOP SIGN IN THE PROCESS.

Diagram

