

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **19-006607**
 Date of Acc: **09/28/19**
 Time of Acc: **20:44** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **STEVENS BRAD**
 Badge #: **71-10**
 Report Date: **09/28/2019**
 Officer Notified: **20:44** Hrs.
 Officer Arrived: **20:57** Hrs.
 Scene Investigated:

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City:
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00287853**
 Y-Coordinate: **04767021**
 Location Literal: **SORREL AVE**
 Description:

Unit 001

Driver Name - Last: NIEUWENHUIS	Bus Use:	Transported to:
First: KELLY		
Middle: VERN	Drvr Distractions: 97 - OTHER DISTRACTION INSIDE VEHICLE (EXPLAIN IN NARRATIVE)	Transported by:
City: PRIMGHAR	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip: 51245	Most Damaged Area: 10 - FRONT DRIVER SIDE	Cont. Circum., Drvr: 42 - FTYROW: MAKING LEFT TURN
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Male	Rpr/Rplc Cost: \$8,913.00	Carrier Name:
Age: 60	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier Address:
CDL: NO	First Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: A	Third Event:	Carrier Zip:
License Endorsmnt: L	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Speed Limit: 55	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 06 - DEPLOYED BOTH FRONT/SIDE	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Year: 2013	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1: 321.320
Vehicle Make: GENERAL MOTORS - GMC	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1: FAIL TO YIELD UPON LEFT TURN
Vehicle Model: SIERRA K1500 DE TRUCK		Citation Charge 2:
Vehicle Style: TRUCK		Citation Charge 3:
Vehicle Color: WHITE - WHI		Citation Charge 4:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		
Vehicle Defect: 01 - NONE		
Vehicle Action: 02 - TURNING LEFT		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 19000109		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last: ROOK	Bus Use:	Transported to: MERCY ONE-PRIMGHAR
First: JACOB		
Middle: STEVEN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: JESSE CHRISTOPHERSON-FRIEND
City: PRIMGHAR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51245		
Suffix:	Point of Init Impact: 10 - FRONT DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 22	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$800.00	
License State: IA	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		
License Restrictions:	Second Event: 01 - RAN OFF ROAD, RIGHT	Carrier Name:
Speed Limit: 55		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1		
Vehicle Year: 2001		Number of Axles:
Vehicle Make: PONTIAC - PONT		HazMat Involvement:
Vehicle Model: MONTANA		HazMat Placard:
Vehicle Style: VAN	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Color: BLACK - BLK		HazMat Released?:
Vehicle Config: 04 - PASSENGER VAN (SEATS <9)	Abg Switch Stat:	Converter Dolly:
Vehicle Defect: 01 - NONE	Abg Deploy: 05 - DEPLOYED SIDE OF PERSON	GVWR:
		Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
	Ejection: 1 - NOT APPLICABLE	
Tow: 3 - DISABLED - OFFICER ARRANGED	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
		Citation Charge 2:
Tow #: 19000110	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	
Initial Trvl Dir: 02 - EAST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 05 - PARENT/SPOUSE/FRIEND	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 02 - HEAD-ON (FRONT TO FRONT)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 12 - FOUR-WAY INTERSECTION
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit 1 was westbound on 430th Street and attempted to make a lefthand turn onto Sorrel Avenue. Unit 2 was eastbound on 430th Street. Driver of Unit 1 stated he looked down inside of his vehicle and then when he looked up, Unit 2 was in the path of his lefthand turn. Unit 1 struck Unit 2 causing Unit 2 to enter the south ditch. Unit 1 was disabled on the roadway.

Diagram

