

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 20001533	Report to All Drivers:	At Intersection with:
Date of Acc: 03/06/20	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 17:24 Hrs.	Private Property: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	County: O'BRIEN - 71	Direction 1:
Officer: DEPUTY JETT KORVER	Acc Loc City:	Distance 2:
Badge #: 71-8	Acc Dir From City:	Direction 2:
Report Date: 03/06/2020	Closest City:	X-Coordinate: 00272059
Officer Notified: 17:26 Hrs.	Miles From City:	Y-Coordinate: 04778359
Officer Arrived: 17:35 Hrs.	Road, Street, HWay:	Location Literal: L036/NETTLE AVE MEASURING
Scene Investigated: YES	Definable Location:	Description: 1486 FEET SOUTH FROM 360TH ST AND L036/NETTLE AVE
	Milepost Number:	

Unit 001

Driver Name - Last: GINGER	Bus Use:	Transported to:
First: DANIEL		
Middle: THOMAS	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SHELDON		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51201-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
Age: 16	Undrrid/Ovrid: 2 - UNDERRIDE, COMPARTMENT I	
CDL: NO	Rpr/Rplc Cost: \$3,000.00	
License State: IA	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: C	First Event: 13 - ANIMAL (AVOIDED HITTING)	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: Y	Second Event: 31 - ANIMAL	Carrier City:
Speed Limit: 55		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event: 42 - BRIDGE/BRIDGE RAIL PARAPET	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE	Most Harmful Event: 42 - BRIDGE/BRIDGE RAIL PARAPET	HazMat Involvement:
Total Occupants: 1	Abg Switch Stat: 03 - NOT DEPLOYED	HazMat Placard:
Vehicle Year: 2003	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Make: BUICK - BUIC	Ejection: 2 - NOT EJECTED	HazMat Released?:
Vehicle Model: LES	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Style: 4D	Occpnt Protect: 99 - UNKNOWN	GVWR:
Vehicle Color: WHITE - WHI		Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Vehicle Defect: 01 - NONE	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT ONE SWERVED TO AVOID A DEER AND HIT THE GUARD RAIL BEFORE A BRIDGE IN THE 3600 MILE OF NETTLE AVE.

