

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 20002192	Report to All Drivers:	At Intersection with:
Date of Acc: 04/03/20	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 08:19 Hrs.	Private Property: NO	Distance 1:
Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF	County: O'BRIEN - 71	Direction 1:
Officer:	Acc Loc City:	Distance 2:
DEPUTY JETT KORVER	Acc Dir From City:	Direction 2:
Badge #: 71-8	Closest City:	X-Coordinate: 00281831
Report Date: 04/03/2020	Miles From City:	Y-Coordinate: 04782252
Officer Notified: 08:21 Hrs.	Road, Street, HWay:	Location Literal: L048/REDWING AVE
Officer Arrived: 08:29 Hrs.	Definable Location:	Description: MEASURING 1641 FEET NORTH FROM 340TH ST AND L048/REDWING AVE
Scene Investigated: YES	Milepost Number:	

Unit 001

Driver Name - Last: PELZEL	Bus Use:	Transported to:
First: MARCUS		
Middle: DWAYNE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: SAN ANGELO	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: TX	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Zip: 76905-0000	Most Damaged Area: 13 - TOP OF VEHICLE	Cont. Circum., Drvr: 05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Suffix:	Undrrid/Ovrid: 9 - UNKNOWN	
Gender: Male	Rpr/Rplc Cost: \$40,000.00	Carrier Name:
Age: 24	Ext of Damage: 5 - SEVERE, VEHICLE TOTALED	Carrier Address:
CDL: NO	First Event: 03 - RAN OFF ROAD, LEFT	Carrier City:
License State: TX	Second Event: 20 - OVERTURN/ROLLOVER	Carrier State:
License Class: C	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: A	Most Harmful Event: 20 - OVERTURN/ROLLOVER	Number of Axles:
Speed Limit: 55	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 06 - DEPLOYED BOTH FRONT/SIDE	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Year: 2019	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: CHEVROLET - CHEV	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: SILVERADO 2500		Cit Chrg Code 2:
Vehicle Style: PK		Citation Charge 2:
Vehicle Color: WHITE - WHI		Citation Charge 3:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 20000021		
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 01 - NOT OBSCURED		

Property Damage 001

Object Damaged: FIELD FENCE	Company Owner Name:
Estimate of Damage: \$100.00	City:
Owner's Name - Last:	State:
First:	Zip Code:
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 02 - CLOUDY	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 03 - ICE/FROST	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 20 - OVERTURN/ROLLOVER
Type:	
Workers Present:	

Narrative

Unit one was south bound in the 3700 mile of Redwing Ave. Unit one lost control on the ice covered road and entered the east ditch, rolling once, and coming to a rest facing

north with the rear of the vehicle hitting a field fence.

Diagram

