

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	20-003044	Report to All Drivers:		At Intersection with:	
Date of Acc:	05/17/20	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	11:09 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY JETT KORVER	Acc Loc City:		Distance 2:	
Badge #:	71-8	Acc Dir From City:		Direction 2:	
Report Date:	05/17/2020	Closest City:		X-Coordinate:	00297689
Officer Notified:	12:09 Hrs.	Miles From City:		Y-Coordinate:	04773191
Officer Arrived:	12:44 Hrs.	Road,Street,HWay:		Location Literal Description:	390TH ST MEASURING 438 FEET EAST FROM M012/VINE AVE AND 390TH ST AND B040/390TH ST
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	JOHNSON	Bus Use:		Transported to:	
First:	ALLISA	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	MAE	Traffic Controls:	04 - STOP SIGNS	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SIoux CITY	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	03 - EXCEEDED AUTHORIZED SPEED, 05 - DRIVING TOO FAST FOR CONDITIONS
Zip:	51101	Undrriid/Ovrid:	9 - UNKNOWN		
Suffix:		Rpr/Rplc Cost:	\$2,000.00		
Gender:	Female	Ext of Damage:	4 - DISABLING DAMAGE	Carrier Name:	
Age:	23	First Event:	02 - RAN OFF ROAD, STRAIGHT	Carrier Address:	
CDL:	NO	Second Event:	01 - RAN OFF ROAD, RIGHT	Carrier City:	
License State:	IA	Third Event:	44 - DITCH	Carrier State:	
License Class:	C	Fourth Event:		Carrier Zip:	
License Endorsmnt:		Most Harmful Event:	44 - DITCH	Cargo Body Type:	01 - NOT APPLICABLE
License Restrictions:		Abg Switch Stat:		Number of Axles:	
Speed Limit:	55	Abg Deploy:	04 - DEPLOYED FRONT OF PERSON	HazMat Involvement:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	HazMat Placard:	
Driver Condition:	01 - APPARENTLY NORMAL	Ejection:	2 - NOT EJECTED	Placard #:	
Alcohol Test Given:	NO	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:	
Drug Test Given:	1 - NONE	Occpnt Protect:	03 - SHOULDER AND LAP BELT USED	Converter Dolly:	
Total Occupants:	1	Source of Trans:	01 - NOT TRANSPORTED	GVWR:	
Vehicle Year:	2006	Died at Scene:	01 - NOT APPLICABLE	Cit Chrg Code 1:	321.285
Vehicle Make:	BUICK - BUIC			Citation Charge 1:	SPEEDING 55 OR UND ZONE (11 THRU 15 OVER)
Vehicle Model:	LCR			Cit Chrg Code 2:	321.322(1)
Vehicle Style:	4D			Citation Charge 2:	FAIL TO OBEY STOP SIGN
Vehicle Color:	WHITE - WHI				
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 3:	321.288(1)
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	2 - DISABLED - PRIVATELY ARRANGED				
Tow #:					
Initial Trvl Dir:	02 - EAST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	01 - NONE APPARENT
Light Conditions:	1 - DAYLIGHT	Roadway:	02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions:	05 - RAIN	Type of Road Junc/Feat:	12 - FOUR-WAY INTERSECTION
Surface Conditions:	02 - WET	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

Driver was East bound on B40, traveling at 70mph in a 55mph zone. Driver stated she didn't realize there was stop sign and couldn't stop. (There are rumble strips and a stop ahead sign posted.) Driver ran the stop sign at B40 and M12 and proceeded onto 390th St which is a gravel road where she lost control of the vehicle and entered the south ditch with the car facing northwest.

Diagram

