

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	S20-004803	Report to All Drivers:		At Intersection with:	
Date of Acc:	07/24/20	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	21:26 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY KEVEN VANMEETEREN	Acc Loc City:		Distance 2:	
Badge #:	71-7	Acc Dir From City:		Direction 2:	
Report Date:	07/24/2020	Closest City:		X-Coordinate:	00285206
Officer Notified:	21:26 Hrs.	Miles From City:		Y-Coordinate:	04786738
Officer Arrived:	21:29 Hrs.	Road,Street,HWay:		Location Literal Description:	US 59/ROOSEVELT AVE
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	CALE-STEINBECK	Bus Use:		Transported to:	
First:	DIANE	Drvr Distractions:	02 - NOT DISTRACTED	Transported by:	
Middle:	MARIE	Traffic Controls:		Special Veh Func:	
City:	EMMETSBURG	Point of Init Impact:		Emergency Status:	
State:	IA	Most Damaged Area:		Cont. Circum., Drvr:	88 - NO IMPROPER ACTION
Zip:	50536-0000	Undrrid/Ovrid:			
Suffix:		Rpr/Rplc Cost:	\$2,000.00		
Gender:	Female	Ext of Damage:		Carrier Name:	
Age:	52	First Event:		Carrier Address:	
CDL:	NO	Second Event:		Carrier City:	
License State:	IA	Third Event:		Carrier State:	
License Class:	C	Fourth Event:		Carrier Zip:	
License Endorsmnt:		Most Harmful Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Restrictions:	B	Abg Switch Stat:		Number of Axles:	
Speed Limit:		Abg Deploy:		HazMat Involvement:	
Seating Position:		Trapped:		HazMat Placard:	
Driver Condition:		Ejection:		Placard #:	
Alcohol Test Given:	NO	Ejection Path:		HazMat Released?:	
Drug Test Given:	1 - NONE	Occpnt Protect:		Converter Dolly:	
Total Occupants:	01			GVWR:	
Vehicle Year:	2014			Cit Chrg Code 1:	
Vehicle Make:	DODGE - DODG			Citation Charge 1:	
Vehicle Model:	AVN			Cit Chrg Code 2:	
Vehicle Style:	4D			Citation Charge 2:	
Vehicle Color:	RED - RED			Citation Charge 3:	
Vehicle Config:	01 - PASSENGER CAR			Citation Charge 4:	
Vehicle Defect:					
Vehicle Action:					
Tow:	1 - DRIVEN AWAY				
Tow #:					
Initial Trvl Dir:					
Vision Obscured:					
		Source of Trans:	01 - NOT TRANSPORTED		
		Died at Scene:	01 - NOT APPLICABLE		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash:
Type:	31 - ANIMAL
Workers Present:	

Narrative

UNIT 1 SOUTHBOUND ON HWY 59 WHEN A DEER CAME OUT OF THE DITCH AND HIT THE SIDE OF THE VEHICLE.

Diagram

