

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>S20-005344</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>08/12/20</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>19:06</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>O'BRIEN COUNTY SHERIFF'S OFF</b>	County:	<b>O'BRIEN - 71</b>	Direction 1:	
Officer:	<b>DEPUTY KEVEN VANMEETEREN</b>	Acc Loc City:		Distance 2:	
Badge #:	<b>71-7</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>08/12/2020</b>	Closest City:		X-Coordinate:	<b>00268650</b>
Officer Notified:	<b>19:08</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04770818</b>
Officer Arrived:	<b>19:16</b> Hrs.	Road,Street,HWay:		Location Literal Description:	<b>MONROE AVE AND 410TH ST</b>
Scene Investigated:	<b>YES</b>	Definable Location:			
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>WATERMAN</b>	Bus Use:		Transported to:	<b>N/A</b>
First:	<b>AMY</b>	Drvr Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	<b>N/A</b>
Middle:	<b>MARIE</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>HAWARDEN</b>	Point of Init Impact:	<b>01 - FRONT PASSENGER SIDE CORNER</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>01 - FRONT PASSENGER SIDE CORNER</b>	Cont. Circum., Drvr:	<b>47 - FTYROW: AT UNCONTROLLED INTERSECTION</b>
Zip:	<b>51023</b>	Undrrid/Ovrid:	<b>1 - NONE</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$55,000.00</b>	Carrier Address:	
Gender:	<b>Female</b>	Ext of Damage:	<b>5 - SEVERE, VEHICLE TOTALED</b>	Carrier City:	
Age:	<b>44</b>	First Event:	<b>06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)</b>	Carrier State:	
CDL:	<b>NO</b>	Second Event:	<b>33 - VEHICLE IN TRAFFIC</b>	Carrier Zip:	
License State:	<b>IA</b>	Third Event:	<b>42 - BRIDGE/BRIDGE RAIL PARAPET</b>	Cargo Body Type:	<b>01 - NOT APPLICABLE</b>
License Class:	<b>C</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:	<b>L</b>	Most Harmful Event:	<b>33 - VEHICLE IN TRAFFIC</b>	HazMat Involvement:	
License Restrictions:	<b>B</b>	Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>55</b>	Abg Deploy:	<b>06 - DEPLOYED BOTH FRONT/SIDE</b>	Placard #:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>2 - NOT EJECTED</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:	<b>321.319</b>
Total Occupants:	<b>01</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Citation Charge 1:	<b>FAILURE TO YIELD TO VEHICLE ON RIGHT</b>
Vehicle Year:	<b>2019</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:	
Vehicle Make:	<b>CADILLAC - CADI</b>			Citation Charge 2:	
Vehicle Model:	<b>ESC</b>			Citation Charge 3:	
Vehicle Style:	<b>UT</b>			Citation Charge 4:	
Vehicle Color:	<b>GRAY - GRY</b>				
Vehicle Config:	<b>03 - SPORT UTILITY VEHICLE</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>				
Tow:	<b>3 - DISABLED - OFFICER ARRANGED</b>				
Tow #:	<b>20-0067</b>				
Initial Trvl Dir:	<b>04 - WEST</b>				
Vision Obscured:	<b>02 - TREES/CROPS</b>				

**Unit 002**

Driver Name - Last: <b>THEISEN</b>	Bus Use:	Transported to: <b>ORANGE CITY HOSPITAL</b>
First: <b>JAMIE</b>		
Middle: <b>LYNN</b>	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by: <b>HOSPERS AMBULANCE</b>
City: <b>MARCUS</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>51035</b>		
Suffix:	Point of Init Impact: <b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Female</b>	Most Damaged Area: <b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
Age: <b>21</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$5,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>5 - SEVERE, VEHICLE TOTALED</b>	
License Class: <b>C</b>	First Event: <b>06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)</b>	Carrier Name:
License Endorsmnt:	Second Event: <b>33 - VEHICLE IN TRAFFIC</b>	Carrier Address:
License Restrictions:	Third Event: <b>42 - BRIDGE/BRIDGE RAIL PARAPET</b>	Carrier City:
Speed Limit: <b>55</b>	Fourth Event:	Carrier State:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Most Harmful Event: <b>33 - VEHICLE IN TRAFFIC</b>	Carrier Zip:
Driver Condition: <b>99 - UNKNOWN</b>	Abg Switch Stat: <b>03 - NOT DEPLOYED</b>	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Alcohol Test Given: <b>NO</b>	Abg Deploy:	Number of Axles:
Drug Test Given: <b>1 - NONE</b>	Trapped: <b>2 - EXTRICATED BY NON-MECHAN</b>	HazMat Involvement:
Total Occupants: <b>01</b>	Ejection: <b>2 - NOT EJECTED</b>	HazMat Placard:
Vehicle Year: <b>2003</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Placard #:
Vehicle Make: <b>CHEVROLET - CHEV</b>	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	HazMat Released?:
Vehicle Model: <b>MOC</b>	Source of Trans: <b>03 - EMS GROUND</b>	Converter Dolly:
Vehicle Style: <b>2D</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	GVWR:
Vehicle Color: <b>BLUE, DARK - DBL</b>		Cit Chrg Code 1:
Vehicle Config: <b>01 - PASSENGER CAR</b>		Citation Charge 1:
Vehicle Defect: <b>01 - NONE</b>		Cit Chrg Code 2:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		Citation Charge 2:
Tow: <b>3 - DISABLED - OFFICER ARRANGED</b>		Citation Charge 3:
Tow #: <b>20-0068</b>		Citation Charge 4:
Initial Trvl Dir: <b>03 - SOUTH</b>		
Vision Obscured: <b>02 - TREES/CROPS</b>		

**Property Damage 001**

Object Damaged: <b>BRIDGE SIGN</b>	Company Owner Name: <b>O'BRIEN COUNTY</b>
Estimate of Damage: <b>\$100.00</b>	City: <b>PRIMGHAR</b>
Owner's Name - Last:	State: <b>IA</b>
First:	Zip Code: <b>51245</b>
Middle:	
Suffix:	

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>07 - SIDESWIPE, OPPOSITE DIRECTION</b>	Environment: <b>03 - VISUAL OBSTRUCTION</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	Type of Road Junc/Feat: <b>12 - FOUR-WAY INTERSECTION</b>
Surface Conditions: <b>10 - GRAVEL</b>	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Type:	
Workers Present:	

**Narrative**

UNIT 1 WESTBOUND ON 410TH ST, UNIT 2 SOUTHBOUND ON MONROE AVE. DUE TO INTERSECTION OF 410TH ST/MONROE HAVING CORN FIELDS AT THAT INTERSECTION BOTH UNITS FAILED TO SEE EACH OTHER AND COLLIDED IN THE INTERSECTION. UNIT 1 CAME TO REST ON A BRIDGE RAIL AND UNIT 2 ENTERED THE DITCH IN THE SW CORNER OF THE INTERSECTION AND LANDED WITH THE REAR OF THE VEHICLE CAUGHT ON THE BRIDGE EMBANKMENT.

Diagram

