

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	20-007721	Report to All Drivers:		At Intersection with:	
Date of Acc:	11/10/20	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	23:45 Hrs.	Private Property:	NO	Distance 1:	
Name of Agency:	O'BRIEN COUNTY SHERIFF'S OFF	County:	O'BRIEN - 71	Direction 1:	
Officer:	DEPUTY JETT KORVER	Acc Loc City:		Distance 2:	
Badge #:	71-8	Acc Dir From City:		Direction 2:	
Report Date:	11/11/2020	Closest City:		X-Coordinate:	00281194
Officer Notified:	23:48 Hrs.	Miles From City:		Y-Coordinate:	04784998
Officer Arrived:	00:06 Hrs.	Road, Street, HWay:		Location Literal Description:	US 18/320TH ST MEASURING 2420 FEET WEST FROM L048/REDWING AVE AND US 18/320TH ST
Scene Investigated:	YES	Definable Location:			
		Milepost Number:			

Unit 001

Driver Name - Last:	FAULKNER	Bus Use:		Transported to:	
First:	RAOUL	Drvr Distractions:	10 - PASSENGER	Transported by:	
Middle:	ALEXANDER	Traffic Controls:	01 - NO CONTROLS PRESENT	Special Veh Func:	01 - NO SPECIAL FUNCTION
City:	SANBORN	Point of Init Impact:	12 - FRONT MIDDLE	Emergency Status:	01 - NOT APPLICABLE
State:	IA	Most Damaged Area:	12 - FRONT MIDDLE	Cont. Circum., Drvr:	05 - DRIVING TOO FAST FOR CONDITIONS, 06 - LOST CONTROL
Zip:	51248	Undrriid/Ovrid:	9 - UNKNOWN		
Suffix:		Rpr/Rplc Cost:	\$2,000.00	Carrier Name:	
Gender:	Male	Ext of Damage:	2 - MINOR DAMAGE	Carrier Address:	
Age:	49	First Event:	04 - CROSSED CENTERLINE (UNDIVIDED)	Carrier City:	
CDL:	NO	Second Event:	03 - RAN OFF ROAD, LEFT	Carrier State:	
License State:	IA	Third Event:	44 - DITCH	Carrier Zip:	
License Class:	C	Fourth Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:		Most Harmful Event:	44 - DITCH	Number of Axles:	
License Restrictions:		Abg Switch Stat:		HazMat Involvement:	
Speed Limit:	55	Abg Deploy:	03 - NOT DEPLOYED	HazMat Placard:	
Seating Position:	01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped:	1 - NOT TRAPPED/APPLICABLE	Placard #:	
Driver Condition:	06 - UNDER THE INFLUENCE O	Ejection:	2 - NOT EJECTED	HazMat Released?:	
Alcohol Test Given:	YES	Ejection Path:	01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:	
Drug Test Given:	1 - NONE	Occpnt Protect:	99 - UNKNOWN	GVWR:	
Total Occupants:	2	Source of Trans:	01 - NOT TRANSPORTED	Cit Chrg Code 1:	321.288(1)
Vehicle Year:	2002	Died at Scene:	01 - NOT APPLICABLE	Citation Charge 1:	FAILURE TO MAINTAIN CONTROL
Vehicle Make:	CHRYSLER - CHRY			Cit Chrg Code 2:	321J.2(2)(A)
Vehicle Model:	300M			Citation Charge 2:	OWI 1ST OFFENSE
Vehicle Style:	4D			Citation Charge 3:	
Vehicle Color:	BLUE - BLU			Citation Charge 4:	
Vehicle Config:	01 - PASSENGER CAR				
Vehicle Defect:	01 - NONE				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				
Tow:	6 - ABANDONED/LEFT AT SCENE				
Tow #:					
Initial Trvl Dir:	04 - WEST				
Vision Obscured:	01 - NOT OBSCURED				

Accident Environment

First Harmful Event Loc:	01 - ON ROADWAY	Roadway Characteristics	
Manner of Crash/Collision:	01 - NON-COLLISION (SINGLE VEHICLE)	Environment:	02 - WEATHER CONDITION
Light Conditions:	5 - DARK, ROADWAY NOT LIGHTED	Roadway:	02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions:	03 - FOG, SMOKE, SMOG	Type of Road Junc/Feat:	01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions:	03 - ICE/FROST	FRA No.:	
Workzone Related:	NO	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	44 - DITCH
Type:			
Workers Present:			

Narrative

Unit one was traveling too fast for conditions and the driver lost control, crossed the center line, and entered the south ditch.

Diagram

