

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **21-000139**
 Date of Acc: **01/08/21**
 Time of Acc: **17:50** Hrs.
 Name of Agency: **O'BRIEN COUNTY SHERIFF'S OFF**
 Officer: **DEPUTY TIMOTHY ROHRBAUGH**
 Badge #: **71-5**
 Report Date: **01/08/2021**
 Officer Notified: **17:50** Hrs.
 Officer Arrived: **18:04** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **O'BRIEN - 71**
 Acc Loc City: **PRIMGHAR - 6240**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00286417**
 Y-Coordinate: **04773847**
 Location Literal: **1ST ST NE**
 Description:

Unit 001

Driver Name - Last: **FOXHOVEN**
 First: **TONY**
 Middle: **LEE**
 City: **PRIMGHAR**
 State: **IA**
 Zip: **51245-0000**
 Suffix:
 Gender: **Male**
 Age: **46**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions: **B**
 Speed Limit: **35**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **2**
 Vehicle Year: **2020**
 Vehicle Make: **NISSAN - NISS**
 Vehicle Model: **VRS**
 Vehicle Style: **SD**
 Vehicle Color: **GRAY - GRY**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **02 - TURNING LEFT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **03 - SOUTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **05 - REAR PASSENGER SIDE CORNER**
 Most Damaged Area: **06 - REAR MIDDLE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$10,000.00**
 Ext of Damage: **3 - FUNCTIONAL DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
5 - UNINJURED
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **42 - FTYROW: MAKING LEFT TURN**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1: **321.320**
 Citation Charge 1: **FAIL TO YIELD UPON LEFT TURN**
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: RODGER	Bus Use:	Transported to:
First: TAYLOR		
Middle: JAE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: PAULLINA		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51046		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 02 - FRONT PASSENGER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 32	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$10,000.00	
License State: IA	Ext of Damage: 4 - DISABLING DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		Carrier Name:
License Restrictions: B		Carrier Address:
Speed Limit: 35		Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given: NO	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 2	Fourth Event:	Number of Axles:
Vehicle Year: 2016		HazMat Involvement:
Vehicle Make: CHEVROLET - CHEV		HazMat Placard:
Vehicle Model: TRV	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Style: SW		HazMat Released?:
Vehicle Color: WHITE - WHI	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Tow: 3 - DISABLED - OFFICER ARRANGED	Ejection: 2 - NOT EJECTED	
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow #: 21-005	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 2:
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 04 - ANGLE, ONCOMING LEFT TURN	Environment: 01 - NONE APPARENT
Light Conditions: 4 - DARK, ROADWAY LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 07 - CROSSOVER-RELATED
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

VEHICLE 1 WAS TRAVELING SOUTH. VEHICLE 2 TRAVELING NORTH. VEHICLE 1 TURN LEFT(FAILING TO YIELD) IN FRONT OF VEHICLE 2.

Diagram

