

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 21-003503
 Date of Acc: 05/28/21
 Time of Acc: 12:43 Hrs.
 Name of Agency: O'BRIEN COUNTY SHERIFF'S OFF
 Officer: VELLEMA LEE
 Badge #: 71-7
 Report Date: 05/28/2021
 Officer Notified: 12:48 Hrs.
 Officer Arrived: 12:59 Hrs.
 Scene Investigated: YES

Report to All Drivers:
 Legal Intervention: NO
 Private Property: YES
 County: O'BRIEN - 71
 Acc Loc City: PRIMGHAR - 6240
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: 00286943
 Y-Coordinate: 04773526
 Location Literal: 3RD ST SE
 Description:

Unit 001

Driver Name - Last: KELLEHER	Bus Use:	Transported to:
First: PAUL		
Middle: JOSEPH	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: PRIMGHAR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51245		
Suffix:	Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER	Cont. Circum., Drvr: 50 - VISION OBSTRUCTED
Age: 76	Undridd/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rpic Cost: \$200.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: B	Second Event:	Carrier City:
Speed Limit:	Third Event:	Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Fourth Event:	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		
Drug Test Given: 1 - NONE	Most Harmful Event: 98 - OTHER (EXPLAIN IN NARRATIVE)	Number of Axles:
Total Occupants: 1	Abg Switch Stat:	HazMat Involvement:
Vehicle Year: 2003	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Vehicle Make: CHEVROLET - CHEV	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Model: SILVERADO 2500	Ejection: 2 - NOT EJECTED	HazMat Released?:
Vehicle Style: PK	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Color: WHITE - WHI	Occpnt Protect: 99 - UNKNOWN	GVWR:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Cit Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 09 - BACKING		
Tow: 1 - DRIVEN AWAY		Cit Chrg Code 2:
		Citation Charge 2:
Tow #:		
Initial Trvl Dir: 02 - EAST		Citation Charge 3:
Vision Obscured: 18 - EXTERIOR ANGLE/BLIND SPOT ON VEHICLE	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

